

FUGRO

**ANNUAL REPORT
JULY 2017 THROUGH JUNE 2018
BIG ROCK MESA LANDSLIDE
ASSESSMENT DISTRICT
City of Malibu, California**

March 2019
Fugro Project No. 04.62160606
Document No. 04.62160606-PR-005(Rev.00)

Big Rock Mesa Landslide Assessment District

Final





FUGRO

ANNUAL REPORT JULY 2017 THROUGH JUNE 2018 BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT City of Malibu, California

March 2019
Fugro Project No. 04.62160606
Document No. 04.62160606-PR-005(Rev.00)

Prepared for: City of Malibu
Big Rock Mesa Landslide Assessment District
23825 Stuart Ranch Road
Malibu, California 90265

Rev.	Status	Prepared	Reviewed	Approved	Date
00	Final	DMT	MQP	MQP	March 8, 2019
A	Draft for Review	DMT	MQP	MQP	February 12, 2019



FUGRO

4820 McGrath Street, Suite 100
Ventura, California 93003
T +1 805 650 7000
F +1 805 650 7010
www.fugro.com

Fugro Project No. 04.62160606
Document No. 04.62160606-PR-005(Rev.00)
March 8, 2019

Big Rock Mesa Landslide Assessment District
23825 Stuart Ranch Road
Malibu, California 90265

Attention: Mr. Rob DuBoux, Esq., P.E.

Annual Report of Maintenance and Monitoring, July 2017 through June 2018, Big Rock Mesa Landslide Assessment District, City of Malibu, California

Dear Mr. DuBoux,

Fugro is pleased to present the annual report of maintenance and monitoring for the Big Rock Mesa Landslide Assessment District. This report summarizes the monitoring and maintenance activities completed during the period of July 2017 through June 2018.

Fugro appreciates this opportunity to serve the City of Malibu and the District homeowners. Please contact David Thornhill or Matt Pollard at (805) 650-7000 if you have any questions regarding this report.

Sincerely,

Fugro USA Land, Inc.

David M. Thornhill, P.E.

Project Engineer/Lead Technician



Matthew Q. Pollard, P.E.

Associate Engineer/Project Manager



Distribution: One electronic copy to Mr. Rob DuBoux, Esq., P.E.

One electronic copy to City of Malibu Geotechnical Staff



CONTENTS

1. INTRODUCTION.....1

1.1 Authorization 1

1.2 Background 1

1.3 Scope of Work..... 1

1.4 Report Organization 2

1.5 Report Availability..... 2

2. MONITORING3

2.1 Rainfall Data 3

2.2 Master Water Meter..... 3

2.3 Groundwater Level Monitoring 3

2.3.1 Pacific Coast Highway (PCH) Region 5

2.3.2 Bluff Region 5

2.3.3 Eastern Mesa Region 6

2.3.4 Central Mesa Region 7

2.3.5 Western Extension Region 7

2.3.6 Headscarp Region 8

2.4 Dewatering Well Production 8

2.5 Hydrauger Production 8

2.6 Slope Inclinometers..... 8

2.6.1 Pacific Coast Highway Region..... 9

2.6.2 Bluff Region 9

2.6.3 Eastern Mesa Region 9

2.6.4 Central Mesa Region 10

2.6.5 Western Extension Region 10

2.6.6 Headscarp Region 10

2.7 Water Quality Monitoring..... 10

2.7.1 Regional Board Requirements..... 10

2.7.2 Water-Quality Results 11

3. DEWATERING FACILITY MAINTENANCE.....13

3.1 Capital Improvements 13

3.2 Facility Maintenance 13

4. SUMMARY AND CONCLUSIONS14

4.1 Annual Summary..... 14

4.2 Concluding Comments 15

5. REFERENCES.....16



TABLES IN THE MAIN TEXT

	Page
Table 1. Summary of Average Groundwater Elevations by Area.....	5
Table 2. Summary of Completed Facility Maintenance.....	13

PLATES

Site Location Map.....	1
Dewatering Facilities Map.....	2
Rainfall Graph.....	3
Summary of Groundwater Levels, Dewatering, & Rainfall.....	4
Total Dewatering Production and Total Water Consumption.....	5
Groundwater Elevation Map May 1995 and May 2018.....	6a
Change in Groundwater Elevation Map May 1995 to May 2018.....	6b
Change in Groundwater Elevation Map May 2016 to May 2018.....	6c

APPENDICES

APPENDIX A

GROUNDWATER LEVEL DATA

Piezometer Information – Standpipe Piezometers.....	Plate A-1a
Piezometer Information – Pneumatic Piezometers.....	Plate A-1b
Groundwater Elevation Data Analysis.....	Plate A-2a
Groundwater Elevation Data Analysis.....	Plate A-2b
Groundwater Elevation Data - PCH Region (Western Half).....	Plate A-3a
Groundwater Elevation Data - PCH Region (Eastern Half).....	Plate A-3b
Groundwater Elevation Data - Bluff Region.....	Plate A-4
Groundwater Elevation Data - Eastern Mesa Region.....	Plate A-5
Groundwater Elevation Data - Central Mesa Region.....	Plate A-6a
Groundwater Elevation Data - Central Mesa Region.....	Plate A-6b
Groundwater Elevation Data - Western Extension.....	Plate A-7
Groundwater Elevation Data - Headscarp Area.....	Plate A-8

APPENDIX B

DEWATERING WELL DATA

Dewatering Well Information.....	Plate B-1
Discharge Rate for Dewatering Wells - Eastern Mesa Region.....	Plate B-2a
Discharge Rate for Dewatering Wells - Eastern Mesa Region.....	Plate B-2b
Discharge Rate for Dewatering Wells - Central Mesa Region.....	Plate B-3a
Discharge Rate for Dewatering Wells - Central Mesa Region.....	Plate B-3b
Discharge Rate for Dewatering Wells - Central Mesa Region.....	Plate B-3c



Discharge Rate for Dewatering Wells - Western Extension Plate B-4

APPENDIX C HYDRAUGER DATA

Summary of Hydrauger Information..... Plate C-1
 Discharge Rate for Hydraugers - Eastern Mesa Region Plate C-2a
 Discharge Rate for Hydraugers - Eastern Mesa Region Plate C-2b
 Discharge Rate for Hydraugers - Central Mesa Region Plate C-3a
 Discharge Rate for Hydraugers - Central Mesa Region Plate C-3b
 Discharge Rate for Hydraugers - Western Extension..... Plate C-4

APPENDIX D SLOPE INCLINOMETER PLOT / DATA

Slope Inclinator Information Plate D1
 Cumulative and Incremental Deflection A Direction Plot SP-11 Plate D2-1
 Cumulative and Incremental Deflection B Direction Plot SP-11 Plate D2-2
 Displacement vs. Time A Direction Plot SP-11 Plate D2-3
 Displacement vs. Time B Direction Plot SP-11 Plate D2-4
 Cumulative and Incremental Deflection A Direction Plot SP-12 Plate D3-1
 Cumulative and Incremental Deflection B Direction Plot SP-12 Plate D3-2
 Displacement vs. Time A Direction Plot SP-12..... Plate D3-3
 Displacement vs. Time B Direction Plot SP-12..... Plate D3-4
 Cumulative and Incremental Deflection A Direction Plot SP-14 Plate D4-1
 Cumulative and Incremental Deflection B Direction Plot SP-14 Plate D4-2
 Displacement vs. Time A Direction Plot SP-14..... Plate D4-3
 Displacement vs. Time B Direction Plot SP-14..... Plate D4-4
 Cumulative and Incremental Deflection A Direction Plot SP-15 Plate D5-1
 Cumulative and Incremental Deflection B Direction Plot SP-15 Plate D5-2
 Displacement vs. Time A Direction Plot SP-15..... Plate D5-3
 Displacement vs. Time B Direction Plot SP-15..... Plate D5-4
 Cumulative and Incremental Deflection A Direction Plot SP-19 Plate D6-1
 Cumulative and Incremental Deflection B Direction Plot SP-19 Plate D6-2
 Displacement vs. Time A Direction Plot SP-19..... Plate D6-3
 Displacement vs. Time B Direction Plot SP-19..... Plate D6-4
 Cumulative and Incremental Deflection A Direction Plot SP-27A..... Plate D7-1
 Cumulative and Incremental Deflection B Direction Plot SP-27A..... Plate D7-2
 Displacement vs. Time A Direction Plot SP-27A Plate D7-3
 Displacement vs. Time B Direction Plot SP-27A Plate D7-4
 Cumulative and Incremental Deflection A Direction Plot SP-29 Plate D8-1
 Cumulative and Incremental Deflection B Direction Plot SP-29 Plate D8-2
 Displacement vs. Time A Direction Plot SP-29..... Plate D8-3
 Displacement vs. Time B Direction Plot SP-29..... Plate D8-4
 Cumulative and Incremental Deflection A Direction Plot SP-30 Plate D9-1
 Cumulative and Incremental Deflection B Direction Plot SP-30 Plate D9-2
 Displacement vs. Time A Direction Plot SP-30..... Plate D9-3



Displacement vs. Time B Direction Plot SP-30.....	Plate D9-4
Cumulative and Incremental Deflection A Direction Plot SP-10.....	Plate D10-1
Cumulative and Incremental Deflection B Direction Plot SP-10.....	Plate D10-2
Displacement vs. Time A Direction Plot SP-10.....	Plate D10-3
Displacement vs. Time B Direction Plot SP-10.....	Plate D10-4
Cumulative and Incremental Deflection A Direction Plot SP-28.....	Plate D11-1
Cumulative and Incremental Deflection B Direction Plot SP-28.....	Plate D11-2
Displacement vs. Time A Direction Plot SP-28.....	Plate D11-3
Displacement vs. Time B Direction Plot SP-28.....	Plate D11-4
Cumulative and Incremental Deflection A Direction Plot SP-32.....	Plate D12-1
Cumulative and Incremental Deflection B Direction Plot SP-32.....	Plate D12-2
Displacement vs. Time A Direction Plot SP-32.....	Plate D12-3
Displacement vs. Time B Direction Plot SP-32.....	Plate D12-4
Cumulative and Incremental Deflection A Direction Plot PC-1.....	Plate D13-1
Cumulative and Incremental Deflection B Direction Plot PC-1.....	Plate D13-2
Displacement vs. Time A Direction Plot PC-1.....	Plate D13-3
Displacement vs. Time B Direction Plot PC-1.....	Plate D13-4
Cumulative and Incremental Deflection A Direction Plot SP-3.....	Plate D14-1
Cumulative and Incremental Deflection B Direction Plot SP-3.....	Plate D14-2
Displacement vs. Time A Direction Plot SP-3.....	Plate D14-3
Displacement vs. Time B Direction Plot SP-3.....	Plate D14-4
Cumulative and Incremental Deflection A Direction Plot SP-3A.....	Plate D15-1
Cumulative and Incremental Deflection B Direction Plot SP-3A.....	Plate D15-2
Displacement vs. Time A Direction Plot SP-3A.....	Plate D15-3
Displacement vs. Time B Direction Plot SP-3A.....	Plate D15-4
Cumulative and Incremental Deflection A Direction Plot SP-33.....	Plate D16-1
Cumulative and Incremental Deflection B Direction Plot SP-33.....	Plate D16-2
Displacement vs. Time A Direction Plot SP-33.....	Plate D16-3
Displacement vs. Time B Direction Plot SP-33.....	Plate D16-4
Cumulative and Incremental Deflection A Direction Plot SP-9A.....	Plate D17-1
Cumulative and Incremental Deflection B Direction Plot SP-9A.....	Plate D17-2
Displacement vs. Time A Direction Plot SP-9A.....	Plate D17-3
Displacement vs. Time B Direction Plot SP-9A.....	Plate D17-4
Cumulative and Incremental Deflection A Direction Plot SP-16A.....	Plate D18-1
Cumulative and Incremental Deflection B Direction Plot SP-16A.....	Plate D18-2
Displacement vs. Time A Direction Plot SP-16A.....	Plate D18-3
Displacement vs. Time B Direction Plot SP-16A.....	Plate D18-4
Cumulative and Incremental Deflection A Direction Plot SP-17B.....	Plate D19-1
Cumulative and Incremental Deflection B Direction Plot SP-17B.....	Plate D19-2
Displacement vs. Time A Direction Plot SP-17B.....	Plate D19-3
Displacement vs. Time B Direction Plot SP-17B.....	Plate D19-4
Cumulative and Incremental Deflection A Direction Plot SP-24.....	Plate D20-1



Cumulative and Incremental Deflection B Direction Plot SP-24Plate D20-2
 Displacement vs. Time A Direction Plot SP-24.....Plate D20-3
 Displacement vs. Time B Direction Plot SP-24.....Plate D20-4
 Cumulative and Incremental Deflection A Direction Plot SP-34Plate D21-1
 Cumulative and Incremental Deflection B Direction Plot SP-34Plate D21-2
 Displacement vs. Time A Direction Plot SP-34.....Plate D21-3
 Displacement vs. Time B Direction Plot SP-34.....Plate D21-4
 Cumulative and Incremental Deflection A Direction Plot SP-35Plate D22-1
 Cumulative and Incremental Deflection B Direction Plot SP-35Plate D22-2
 Displacement vs. Time A Direction Plot SP-35.....Plate D22-3
 Displacement vs. Time B Direction Plot SP-35.....Plate D22-4
 Cumulative and Incremental Deflection A Direction Plot SP-36Plate D23-1
 Cumulative and Incremental Deflection B Direction Plot SP-36Plate D23-2
 Displacement vs. Time A Direction Plot SP-36.....Plate D23-3
 Displacement vs. Time B Direction Plot SP-36.....Plate D23-4
 Cumulative and Incremental Deflection A Direction Plot SP-20Plate D24-1
 Cumulative and Incremental Deflection B Direction Plot SP-20Plate D24-2
 Displacement vs. Time A Direction Plot SP-20.....Plate D24-3
 Displacement vs. Time B Direction Plot SP-20.....Plate D24-4
 Cumulative and Incremental Deflection A Direction Plot SP-21Plate D25-1
 Cumulative and Incremental Deflection B Direction Plot SP-21Plate D25-2
 Displacement vs. Time A Direction Plot SP-21.....Plate D25-3
 Displacement vs. Time B Direction Plot SP-21.....Plate D25-4
 Cumulative and Incremental Deflection A Direction Plot SP-22Plate D26-1
 Cumulative and Incremental Deflection B Direction Plot SP-22Plate D26-2
 Displacement vs. Time A Direction Plot SP-22.....Plate D26-3
 Displacement vs. Time B Direction Plot SP-22.....Plate D26-4
 Cumulative and Incremental Deflection A Direction Plot SP-23Plate D27-1
 Cumulative and Incremental Deflection B Direction Plot SP-23Plate D27-2
 Displacement vs. Time A Direction Plot SP-23.....Plate D27-3
 Displacement vs. Time B Direction Plot SP-23.....Plate D27-4
 Cumulative and Incremental Deflection A Direction Plot SP-26Plate D28-1
 Cumulative and Incremental Deflection B Direction Plot SP-26Plate D28-2
 Displacement vs. Time A Direction Plot SP-26.....Plate D28-3
 Displacement vs. Time B Direction Plot SP-26.....Plate D28-4

APPENDIX E WATER QUALITY TESTING

Summary of Water Quality Monitoring Data – Third Quarter (Jul.-Sep.) 2017Plate E-1
 Summary of Water Quality Monitoring Data – Fourth Quarter (Oct.-Dec.) 2017Plate E-2
 Summary of Water Quality Monitoring Data – First Quarter (Jan.-Mar.) 2018Plate E-3
 Summary of Water Quality Monitoring Data – Second Quarter (Apr.-Jun.) 2018Plate E-4



1. INTRODUCTION

1.1 Authorization

Fugro USA Land, Inc. (Fugro) performed the work summarized in this report in accordance with our contract with the City of Malibu (City) and consistent with the cost estimate document "Exhibit A - FY 2017-2018 Maintenance Cost Estimate" presented in the Annual Assessment Report (Taussig, 2016).

1.2 Background

Following the activation of the Big Rock Mesa landslide in 1983, the County of Los Angeles (County) established the Big Rock Mesa Landslide Assessment District (Assessment District) in 1989. The Assessment District provides permanent funding to maintain and monitor dewatering facilities with the purpose of reducing landslide movements. The County administered the Assessment District until 1991 when the City of Malibu (City) incorporated. The Assessment District was re-authorized in May 1998 under City of Malibu Resolution No. 98-030. The City has since administered the Assessment District, utilizing consultants to maintain and monitor the district facilities.

1.3 Scope of Work

This annual report summarizes the current monitoring and maintenance of the geotechnical instrumentation and dewatering facilities for the period between July 1, 2017, and June 30, 2018 (hereinafter, the "monitoring period"). Data collected during this monitoring period included the following:

- Annual Rainfall data from Big Rock Mesa rain gauge number 1239, operated by the County of Los Angeles, Department of Public Works – Water Resources Division;
- Monthly groundwater level measurements from 29 standpipes;
- Periodic groundwater measurements from 4 pneumatic piezometers;
- Semi-Monthly to Monthly dewatering production readings from 24 dewatering wells;
- Monthly to Bi-Monthly dewatering production readings from 32 horizontal drains (hydraugers);
- Quarterly, semi-annual, or annual ground deformation readings from 26 slope inclinometers (geotechnical instrumentation);
- Monthly readings of water usage data from the Mesa's master flow meter; and
- Water-quality sampling and analysis for National Pollution Discharge Elimination System (NPDES) compliance.

The operating condition of the instrumentation and dewatering facilities was checked during each field monitoring/observation event and by evaluating preliminary data in the office as they were received. Maintenance was performed as needed based on field observations, preliminary data evaluation, and correspondence from concerned homeowners and tenants.

The scope of our services is limited to monitoring and maintaining the Assessment District facilities. The services that are provided on an annual basis for the Assessment District do not include geologic or engineering evaluations of the stability of the landslide.



1.4 Report Organization

Monitoring data collected during the July 1, 2017 to June 30, 2018, monitoring period are provided herein. The boundary of the Assessment District is illustrated on Plate 1 – Site Location Map. Plate 2 – Dewatering Facilities Map presents the approximate locations of the geotechnical instrumentation and dewatering facilities. Monitoring data are presented in both tabular and graphical form in Appendices A through E, respectively, and as indicated in the table of contents.

1.5 Report Availability

The annual Assessment District reports are available for review at Malibu City Hall. Reports may also be viewed on the City's website at <http://www.malibucity.org>.



2. MONITORING

2.1 Rainfall Data

Plate 3 – Rainfall Graph presents the historical monthly rainfall and average annual rainfall data from October 1968 through June 30, 2018. Data between 1968 and 2004 were obtained from County of Los Angeles Department of Public Works (LADPW) Carbon Canyon Rain Station 447C. Monthly rainfall totals from 2004 to the present were obtained from LADPW Big Rock Mesa Rain Gauge 1239.

Rainfall data indicate that approximately 7.51 inches of precipitation fell during the monitoring period from July 1, 2017, through June 30, 2018. The average annual rainfall from 1968 to 2018 in the “Malibu area” for the same months is approximately 15.58 inches.

However, rainfall data are usually analyzed in terms of the annual “rain season” that covers the time period between October 1 through September 30. Rainfall between October 1, 2017, through September 30, 2018, was approximately 7.36 inches. That is approximately 53 percent lower than the average annual rainfall of 15.69 inches for the “rain seasons” between 1968 and 2018.

Plate 4 – Summary of Groundwater Levels, Dewatering, and Rainfall shows the yearly magnitude of deviation of each years’ rainfall relative to the mean annual rainfall. The graphic also shows the average annual dewatering output (gallons per day, gpd). The data illustrates that the average annual dewatering output increased with below average rainfall for the 2017-2018 monitoring period.

2.2 Master Water Meter

Water usage data are collected by performing monthly readings at the master water meter near the intersection of Rockport Way and Big Rock Drive. The master water meter measures all imported water supplied to the Big Rock Mesa area by Los Angeles County Waterworks District 29. Processed readings are shown as a plot of flow rate versus time on Plate 5. An evaluation of the data indicates the following.

- The recorded water usage rates are cyclic throughout the monitoring year reflecting higher levels of usage during the summer months.
- Periods of higher than average rainfall, such as the springs of 2005 and 2006 and the winters of 2011 and 2017 tend to lead to lower water consumption as landscaping water needs decline.
- There had been a general trend of increasing water consumption from about 1995 to 2008. Water consumption has generally trended downwards since 2008.
- Average monthly water usage for this monitoring year increased slightly from the previous year. Average water usage during the 2017 through 2018 monitoring year was approximately 156,200 gallons per day (gpd), which is approximately 7.4 percent more than the 2016 through 2017 monitoring year average of 145,500 gpd.

2.3 Groundwater Level Monitoring

The groundwater monitoring data collected during the 2017-2018 monitoring period are summarized in Appendix A. Groundwater levels fluctuate throughout the year, and from year to year, in response to



natural and man-made influences. The primary natural influence is varying precipitation. Man-made influences include:

- Infiltration from onsite wastewater treatment systems;
- Infiltration from irrigation;
- Alterations to surface drainage by grading, landscaping, storm drains, and rain gutters;
- Inadvertent water discharges from leaking utilities such as water, irrigation, sewer, storm drain lines as well as from swimming pools; and
- Dewatering activities from pumping dewatering wells and gravity-draining hydraugers.

Our staff typically measures groundwater levels in standpipe piezometers on a monthly basis and in pneumatic piezometers on a semi-annual basis. Monitoring data and graphs illustrating groundwater levels recorded in monitoring wells and pneumatic piezometers for the six physiographic regions of the Big Rock Mesa landslide are presented in Appendix A. Groundwater elevation maps from May 8, 1995, and May 14, 2018, are shown on Plate 6a. A map of the changes in ground water elevation between May 1995 and May 2018 is shown on Plate 6b. A map of the changes in ground water elevation between May 2017 and May 2018 is shown on Plate 6c.

As observed from the available data, groundwater levels rise relatively quickly following significant rainfall and gradually lower after a wet season ends. Groundwater levels recorded in the Assessment District typically peak around late-March to mid-April and have gradually declined through late September to November.

We reviewed groundwater data by evaluating changes that occurred during the monitoring period as well as changes in groundwater levels compared to historical averages (1984 through 2018). To analyze trends in seasonal groundwater fluctuations, the average (mean) annual and highest annual recorded groundwater elevation for each piezometer were calculated (Appendix A) and are summarized in Table 1. Average groundwater elevations presented in Table 1 incorporate measurements from all monitored standpipes. It is important to note that historical reports (prior to 2012) do not include SP-17B, which was installed in February 2012, but the water levels reported since 2012 include measurements from SP-17B in the area average for the Central Mesa Area. Similarly, measured tip pressures from the pneumatic piezometers located throughout the Assessment District have been excluded from the area averages due to the inconsistency and potential error with their readings.



Table 1. Summary of Average Groundwater Elevations by Area

	Total No. of Wells	2017-18 Average Groundwater Elevation (ft)	Change in Average Groundwater from Prior Monitoring Period (ft)	2017-2018 Average Peak Groundwater Elevation (ft)	Change in Average Peak Groundwater Elevation from Prior Monitoring Period (ft)
PCH Region	8	8.7	-0.2	9.8	-1.0
Bluff Region	4	34.2	+0.9	39.8	+0.2
Eastern Mesa	4 ¹	42.9	-15.0	45.2	-40.3
Central Mesa	9	217.7	-0.4	228.1	-3.3
Western Extension	4	380.6	+4.3	387.3	+0.4
Headscarp Region	1	552.3	+0.3	553.8	-0.2

1. Since SP-3 remains dry, the Eastern Mesa area average is based on 3 wells

A summary graph presenting the deviation of peak groundwater elevations for each of the six regions in Big Rock Mesa as compared to the average peak groundwater elevations for each region is presented on the top graph of Plate 4. The bottom graph on Plate 4 compares the average dewatering output (gpd) to the annual deviation from the mean annual rainfall over the same time period.

2.3.1 Pacific Coast Highway (PCH) Region

The PCH Region parallels the coastal highway at the base of the bluff, including the area between the bluff and the Pacific Ocean. The PCH Region includes the southern boundary of the 1983 landslide. The Shoreline fault and landslide rupture surface define both a zone of weakness and a groundwater barrier, extending approximately along the same alignment as the highway.

Groundwater data for the PCH Region are presented as hydrographs on Plate A-3a and A-3b. Groundwater levels in this area are monitored using standpipe piezometers SP-11, 12, 14, 15, 19, 27A, 29, and 30. In general, groundwater elevations in the PCH Region for the 2017-2018 monitoring year decreased slightly. The calculated area average groundwater elevation decreased by 0.2 feet when compared to the 2016-2017 monitoring period and is 0.2 feet above the mean groundwater elevation for the area for the period of record (1987 to 2018). Calculated average water elevations for individual standpipes during the 2017-2018 monitoring period varied by 1 foot or less when compared to average water elevations for the 2016-2017 monitoring year in all standpipes except SP-15, which showed an annual average decrease of 1.8 feet, from 10.6 to 8.8 feet.

2.3.2 Bluff Region

The Bluff Region extends along the top of the slope immediately the north of the PCH Region, and is an area where intense ground cracking was observed during the 1983 landslide. The subsurface materials within the Bluff Region generally have a relatively high secondary permeability due to the level of fracturing that had occurred.



Groundwater data for the Bluff Region are presented as hydrographs on Plate A-4. Groundwater levels in this area are monitored using standpipe piezometers SP-10, 28, 32, and 34, and the pneumatic piezometers installed with SP-34. In general, groundwater elevations for the Bluff Region for the 2017-2018 monitoring year increased slightly. The calculated area average groundwater elevation increased 1.0 feet when compared to the 2016-2017 monitoring period and is 21.0 feet below the mean water level elevation for the area for the period of record.

Calculated average water elevations for standpipes SP-10, SP-28 and SP-32 during the 2017-2018 monitoring year varied by 1 foot or less when compared to average water elevations for the 2016-2017 monitoring year. Groundwater elevations in standpipe SP-34 had declined through December 2016 in response to increased dewatering following installation of dewatering well FW-2 in 2010. After reaching an all-time low in measured groundwater elevation in February 2017, groundwater levels appear to have stabilized.

Pore pressures measured in SP-34 pneumatic piezometer tips 1 and 2 continue to rise and fall in approximate correlation with the standpipe water levels. Standpipe SP-34 pneumatic tip 3 continues to measure 0 PSI and tip 4 is non-functional; therefore, no data for those tips are reported.

2.3.3 Eastern Mesa Region

The Eastern Mesa Region lies between the Bluff Region and Big Rock Mesa Drive east of the Piedra Chica cul-de-sac. Groundwater in this area occurs within low permeability deposits of the Sespe Formation.

Groundwater data for the Eastern Mesa Region is presented as hydrographs on Plate A-5. Groundwater levels in this area are monitored using standpipe piezometers SP-3, -3A, -33, PC-1, and the pneumatic piezometers installed with PC-1. Overall groundwater elevations for the Eastern Mesa for the 2017-2018 monitoring year decreased. The calculated area average groundwater elevation decreased 15.0 feet when compared to the 2016-2017 monitoring period and is 26.2 feet below the mean water level elevation for the area for the period of record.

Measured groundwater elevations in standpipe PC-1 remained consistent throughout the 2017-2018 monitoring period. The previous monitoring year saw a temporary spike in the measured water levels in standpipe PC-1 following significant rain events. A similar spike was not observed during this monitoring year, leading to the decrease of 15 feet in the average groundwater elevation as compared to the 2016-2017 monitoring year. In addition, the December 2017 reading was the lowest measured groundwater elevation for standpipe PC-1 for the period of record. Measured groundwater elevations in standpipe SP-3A also reached a new low in May 2018 for the period of record.

Pore pressures measured in PC-1 pneumatic tips 1 and 3 remained steady throughout the 2017-2018 monitoring year. PC-1 Tip 2 has been reading a pore pressure of 0 PSI since 2011. Tips 4 and 5 five are not functional and no data are reported.



2.3.4 Central Mesa Region

The Central Mesa Region lies between the Bluff Region and Big Rock Mesa Drive, west of the Piedra Chica cul-de-sac. Groundwater within this area generally occurs within moderately permeable landslide deposits derived from the Topanga Formation.

Groundwater data for the Central Mesa Region is presented as hydrographs on Plate A-6a and A-6b. Groundwater levels in this area are monitored using standpipe piezometers SP-9A, 16, 16A, 17, 17A, 17B, 24, 35, 36, and the pneumatic piezometers tips installed with SP-35 and 36. In general, groundwater elevations in the Central Mesa Region for the 2017-2018 monitoring year increased slightly. The calculated area average groundwater elevation increased 0.6 feet when compared to the 2016-2017 monitoring period.

Calculated average water elevations for standpipes during the 2017-2018 monitoring year varied by 2 feet or less when compared to average water elevations for the 2016-2017 monitoring year with the exception of SP-16 (increase of 7.7 feet), SP-16A (increase of 2.6 feet), and SP-35 (decrease of 3.7 feet).

Groundwater elevations in standpipes SP-16 and -16A experienced a steep increase in May and July 2018, likely in response to a temporary shut-down of nearby dewatering well BYA-1 for replacement of the electrical control box. It is anticipated that groundwater levels in SP-16 and -16A will decrease once BYA-1 is returned to normal operation.

Pneumatic piezometer SP-35 Tips 1, 2, and 3 recorded pore pressures rose and fell, approximately correlating with the rise and decline of measured groundwater levels in standpipe SP-35. Pneumatic piezometer SP-35 Tip 4 is not functioning, and no data are reported.

Pneumatic piezometers SP-36 Tip 1 and Tip 2 remained approximately stable during most of the monitoring year corresponding to the static groundwater levels measured in standpipe SP-36. Pneumatic piezometer SP-36 Tip 3 has recorded 0 PSI since installation and no data are reported.

2.3.5 Western Extension Region

The Western Extension Region encompasses approximately 79 acres, from PCH on the south to the upper ridgeline on the north. The region is located immediately west of the active 1983 Big Rock Mesa Landslide area.

Groundwater data for the Western Extension Region is presented as hydrographs on Plate A-7. Groundwater levels in this area are monitored using standpipe piezometers SP-20, -21, -22, and -23. In general, groundwater elevations for the Western Extension Region for the 2017-2018 monitoring year increased. The calculated area average groundwater elevation increased by 4.3 feet when compared to the 2016-2017 monitoring period and was 3.0 feet below the mean groundwater elevation for the area for the period of record.



2.3.6 Headscarp Region

The Headscarp Region borders the Central Mesa Region to the north. The ground surface elevation in the Headscarp Region is higher than other regions in Big Rock Mesa, and groundwater is relatively deep.

Groundwater data for the Headscarp Region is presented as a hydrograph on Plate A-8. Groundwater levels in this area are monitored using standpipe piezometer SP-26. In general, groundwater elevations for the Headscarp Region for the 2017-2018 monitoring year increased slightly. The calculated area average groundwater elevation increased by 0.3 feet when compared to the 2016-2017 monitoring period and was 3.2 feet above the mean groundwater elevation for the area for the period of record.

2.4 Dewatering Well Production

The total production rate for all dewatering wells from 1993 through June 2018 is depicted on Plate 5. Dewatering well information, status and production rates for individual wells are presented on Plates B-1 through B-4 (Appendix B).

The average total well production rate for the monitoring period was approximately 44,445 gpd. This is approximately 12 percent more than the previous year's monitoring period value of 39,697 gpd, and below the historical average production of 52,426 gpd measured from 1993 to the present. Total dewatering well production was affected during the year as mechanical, electrical, or other issues caused wells to intermittently stop or reduce production. Over the course of the 2017-2018 monitoring year, dewatering wells BYA-1, -5, -11, -12, and W-18 had periods without production.

2.5 Hydrauger Production

The total production rate for all hydraugers from 1993 through June 2018 is depicted on Plate 5. Additional data regarding hydraugers and production rates are presented in Appendix C, Plates C-1 through C-4.

The average total hydrauger production rate over the monitoring period was approximately 14,184 gpd. That represents an approximately 4 percent increase in production relative to the previous monitoring period (13,652 gpd).

2.6 Slope Inclinerometers

Fugro monitored 26 slope inclinometers on a quarterly to annual basis to check for subsurface ground deformation through June 2018.

Slope inclinometer measurement plots are presented in Appendix D. Four slope inclinometer plots are prepared for each inclinometer installation:

- The first plot shows the cumulative deflection and incremental deflection for the A-direction.
- The second plot shows the cumulative deflection and incremental deflection for the B-direction.



- The third and fourth plots show displacement versus time for the same period as the first two plots (one for each direction) and the displacement time plots include intermediate readings for each of the years presented.

When reviewing and interpreting the slope inclinometer data plots, instrument limitations and movement history should be considered. Individual plots have been reviewed and interpreted with regard to movement along identified slide planes. Interpreted movement along the identified slide planes is summarized on Plate D1 in Appendix D.

Several inclinometers show some inconsistent changes (typically <0.1 to 0.2 inch), but the potential movement magnitude and orientation is not clear and is not within the reliable accuracy of the instrument. Some of the irregular shapes observed in the deep inclinometers can be attributed to depth position and rotation errors caused by cable length changes, local curvatures within the casings, and significant deviation from vertical during initial installation, which is common to deep inclinometers.

A brief summary of each region is presented below and is summarized on Plate D1. It is important to keep in mind the high sensitivity of the inclinometer probes and the magnitude of the interpreted movements when reviewing the inclinometer data presented in this report. Plate D1 notes the depths at which movement has been interpreted in the past, as well as whether the inclinometer penetrates the basal rupture surface. Shallower depths of historically interpreted movement above the base of the Big Rock Mesa Landslide have also been noted.

2.6.1 Pacific Coast Highway Region

The PCH Region extends along PCH in proximity of the southern boundary of the 1983 Big Rock Mesa landslide. No quantifiable offsets within the inclinometers of the PCH Region were measured during this monitoring period.

2.6.2 Bluff Region

The Bluff Region extends along the top of the slope immediately north of the PCH Region, where intense ground cracking was observed during the 1983 landslide. The inclinometers in that area are deep and show evidence of depth position and rotation errors, associated with cable stretch, casing curvature, and casing deviation from vertical. No quantifiable offsets within the inclinometers of the Bluff Region were measured during this monitoring period.

2.6.3 Eastern Mesa Region

The Eastern Mesa Region extends west to the ends of Inland Lane and the Piedra Chica cul-de-sac. This area is bordered to the north by Big Rock Drive and to the south by the Bluff Region. The inclinometers in the Eastern Mesa Region are deep and show evidence of depth position errors, as well as localized casing curvature, and casing deviation from vertical. No quantifiable offsets along identified shear planes were detected within the inclinometers of the Eastern Mesa Region during the current monitoring year.



2.6.4 Central Mesa Region

The Central Mesa Region is located between the Bluff and Big Rock Mesa Drive and to the west of the Piedra Chica cul-de-sac. The inclinometers in that region are deep and show evidence of depth position errors, probably associated with ground settlement and/or cable stretch. No quantifiable offsets were measured within the inclinometers in the Central Mesa Region during the current monitoring year.

2.6.5 Western Extension Region

The Western Extension Region encompasses approximately 79 acres, from PCH on the south end to the upper ridgeline on the north, immediately west of the 1983 Big Rock Mesa landslide area. The inclinometers in that area are deep and show evidence of depth position errors, probably associated with local casing curvature and casing deviation from vertical. No quantifiable offsets within the inclinometers in the Western Extension Region were measured during the current monitoring year.

2.6.6 Headscarp Region

The Headscarp Region borders the Central Mesa Region to the north. SP-26 is the only inclinometer being measured in this region and, historically, has been the first to move and the last to cease movement in response to heavy rainfall within the assessment district. Inclinometer SP-26 is deep and shows evidence of depth position errors, probably associated with local casing curvatures and casing deviation from vertical. No quantifiable offsets within SP-26 were measured during the current monitoring year.

2.7 Water Quality Monitoring

2.7.1 Regional Board Requirements

Water quality monitoring was completed in general compliance with the NPDES permit, as required by the California Regional Water Quality Control Board (RWQCB).

On March 2, 2004, the RWQCB issued General NPDES permit CAG994004, Order No. R4-2003-011. On October 3, 2008, Order No. R4-2003-0111 was superseded by Order No. R4-2008-0032, providing revised requirements for sampling and analysis. Total chlorine was not a required element of the sampling and testing plan until the end of the second quarter 2010. A revised permit was issued to the City in October 2010 requiring all discharge points to be sampled monthly for all constituents, except for Acute Toxicity, which is to be tested annually. On June 5, 2015, order No. R4-2003-0032 was superseded by general order number R4-2013-0095 (current permit). Fugro conducted water quality monitoring during the 2017-2018 monitoring year consistent with the requirements of the RWQCB NPDES permit, No. R4-2013-0095.

Water produced by assessment district dewatering wells is pumped into the public storm drain system and water flow from the hydraugers is collected through a conveyance line system. Both the storm drain system and the conveyance line system empty into ten culverts on the north side of Pacific Coast Highway. Usually, effluent from several wells and hydraugers drain into a common culvert where they co-mingle with effluent from other sources and then flow under the PCH to a Discharge Point on the beach. The ten beach Discharge Points referred to in the permit are named M-001 through M-010. Other sources of



surface water are collected by the storm-drain system including storm water runoff (during and following precipitation), irrigation runoff, domestic use surface runoff from car washing and hosing-off of driveways, illicit discharges, groundwater seepage, and other possible unidentified sources.

All samples during the 2017-2018 monitoring year were collected directly from the ten beach discharge points with two exceptions: 1) Discharge point M-009 cannot not be located and was instead sampled directly from hydrauger HD-7, which is the only assessment district dewatering source flowing into M-009; and 2) Discharge point M-003 flow was too low for sampling to be practical and, therefore water representative of M-003 was sampled directly from hydrauger HD-41, which provides the vast majority of the dewatering flow to M-003. From October to December 2017, Discharge Point M-003 and its contributing hydrauvers were non-flowing and no sample was collected those months.

Representative samples from each discharge point were collected and analyzed for the entire suite of constituents listed in the permit once per month. Discharge points with analytes that were detected in concentrations exceeding permitted limits were subsequently sampled and tested for that analyte on a weekly basis. After at least three consecutive weekly follow-up samples are measured within permit limits, sampling for that analyte may return to once monthly.

All samples were collected in clean laboratory provided jars, placed in a cooler on ice and delivered to the analytic laboratory under proper chain of custody protocol within method specific holding times, with the exception of total chlorine, pH, and temperature, which were measured in the field during sample collection. One quality control duplicate sample was collected for every monthly sampling event.

2.7.2 Water-Quality Results

Water quality data summary sheets for each quarter of the 2017-2018 monitoring period are provided as Plate E-1 through E-4 in Appendix E.

During the 2017-2018 monitoring year, samples collected from the ten Discharge Points exceeded permitted concentration limits for Biochemical Oxygen Demand, Settleable Solids, Total Suspended Solids, TPH, Zinc, Methylene Blue Activated Substances (MBAS), Turbidity, and Total Chlorine. Most of the permit exceedances occurred over a short duration while some, such as Total Chlorine at M-008 and Zinc concentrations at Discharge Points M-005, and M-008 intermittently exceeded permit limits throughout the monitoring year.

In accordance with the permit, bacteriological testing for Total Coliform, Fecal Coliform and Enterococcus was performed once monthly at each discharge point. With the exception of M-009/HD-7 and M-003/HD-41, results of bacteriological sampling through the 2017-2018 monitoring year consistently or intermittently detected Total Coliform and Enterococcus in concentrations exceeding NPDES general permit limits at each of the Discharge Points. Fecal Coliform was intermittently detected in concentrations exceeding NPDES general permit limits from all discharge points except M-009/HD-7, M-003/HD-41 and M-002. Fugro will continue to monitor and report the results of bacteriological levels once each month in consultation with the RWQCB.



Acute toxicity testing is required once per year under the permit. Acute toxicity was performed during Quarter 4 of 2017. Those results indicate 96 to 100 percent survival rate from all discharge ports

The current permit requires quarterly and annual compliance reporting to the Regional Board. Those water quality reports are more comprehensive and provide details for each sampling event and exceedance. Quarterly and annual permit compliance reports may be downloaded and viewed from the RWQCB website.



3. DEWATERING FACILITY MAINTENANCE

3.1 Capital Improvements

Capital improvement projects are those of larger scale that are budgeted for during the previous year and that in most cases involve subcontracted services and/or extensive coordination with the City or other agencies to complete. Fugro is continuing to work with Southern California Edison and hired subcontractor, Layne Christiansen, to upgrade the replace the electrical control associated with BYA-1. That work will be completed as part of the FY2018-2019 capital improvements.

3.2 Facility Maintenance

The operating status of each dewatering well and hydrauger was checked during each monitoring event. When necessary, repair work was scheduled and undertaken as expeditiously as reasonable - typically within a matter of a few hours to a few days after identifying a problem. Generally, repairs and maintenance consisted of brush clearance, cleaning, and well pump and electrical repairs. Table 2 presents a summary of facility maintenance/repairs that were completed during the 2017-2018 monitoring year.

Table 2. Summary of Completed Facility Maintenance

Facility	Date of Repair	Repair
BYA-9	9/01/17	Brush, bail, and replace pump
BYA-3	9/7/17	Replacement of pump saver
BYA-6A,6B,7 and HD-24	9/28/17	Replacement of broken hydraugers
BYA-6	11/30/17	Fix leak at dewatering well BYA-6
W-2	12/12/17	Fix leak at dewatering well W-2
BYA-6	4/22/18	Replace broken PVC fitting at dewatering well BYA-6
BYA-18	4/22/18	Fix electrical panel

4. SUMMARY AND CONCLUSIONS

4.1 Annual Summary

The general status of the Big Rock Mesa Landslide Assessment District can be summarized as follows:

- The groundwater level in the Big Rock Mesa landslide is the primary factor controlling the stability of the landslide mass. Rises in groundwater level tend to de-stabilize the landslide. Previous episodes of movement of the landslide have been directly related to high groundwater levels. Therefore, controlling the long-term average and peak groundwater levels in the landslide mass is the primary means being used to reduce future movements of the landslide. The primary factors influencing recharge of groundwater to the landslide are: 1) onsite wastewater treatment system discharge, 2) rainfall, 3) irrigation, and 4) water-line and pool leakage.
- Monitoring data related to rainfall and imported water usage indicate the following:
 - Rainfall during the 2017-2018 rain-season period (October to September) was 7.36 inches of precipitation, which is below the historical average annual rainfall during the “rain season” of 15.69 inches. Rainfall during the Malibu “monitoring period” (July 2017 to June 2018) was 7.51 inches of precipitation which is lower than the historical annual average of 15.58 inches per year measured between July and June from 1968 through June 2018.
 - Use of imported water increased approximately 7.4 percent from the previous monitoring year (156,200 gpd versus 145,500 gpd) and is 33 percent above the average usage in 1984 (117,400 gpd).
- Groundwater levels in 29 standpipe piezometers were measured on a monthly basis during the monitoring period. Average groundwater levels measured during the monitoring period were more than 1 foot above long-term average groundwater levels for 8 of the 29 standpipe piezometers. The remaining 21 piezometers indicated a relatively static or lowered groundwater level.
- The average total well production rate for the 2017-2018 monitoring period was approximately 44,445 gpd. This is a 12 percent increase when compared to the previous year’s monitoring period rate of 39,697 gpd and is below the historical average production rate of 52,426 gpd measured between 1993 and the present.
- The average total hydrauger production rate over the 2017-2018 monitoring period was approximately 14,184 gpd. That represents a 4-percent increase in production relative to the previous monitoring period (13,652 gpd).
- Interpretation of inclinometer data shows no quantifiable ground movement in the inclinometers monitored during the 2017 through 2018 monitoring period.
- Water quality monitoring, conducted in general conformance with the requirements of the RWQCB NPDES Permit No. R4-2013-0095, which became effective June 5, 2015, indicate occasional to consistent exceedances for bacteriological analytes at each of the discharge points except for M-003/HD-7 and M-009/HD-41. It was also noted that revising sample locations from the individual facility discharge points back to the beach-side Discharge Points after March 2015 appears to have resulted in detection of exceedances that were not typically present when sampling occurred directly from the individual dewatering facilities within the District during November 2004 to March 2015.



- Routine and minor maintenance was conducted throughout the 2017-2018 monitoring year on the dewatering wells, hydraugers, and conveyance systems. Ongoing maintenance and repair work are essential to maintaining the capacity of the dewatering system.

4.2 Concluding Comments

It is important to recognize that the dewatering facilities installed over the preceding decades are aging and require increasing maintenance and regular replacement. The anticipated lifespan of an average hydrauger is measured in years, not decades. Dewatering wells may last from a few years to several decades. In order to maintain the highest possible efficiency of the existing horizontal drains, cleaning should be conducted on a regular basis.

Dewatering wells should be reviewed on an individual basis and redeveloped, repaired, or replaced as necessary.

The geology throughout the Assessment District is not uniform and varies from one location to another. Areas of low permeability, such as in the Eastern Mesa Region, can limit the dewatering production of individual facilities.

Water conservation throughout the Big Rock Mesa area is essential to reduce groundwater recharge. As previously stated, rainfall and imported (household) water usage are the primary sources of groundwater recharge and are the primary factors controlling the movement of the landslide. Seasonal rainfall is beyond the control of homeowners and the City; therefore, water conservation is the most critical remaining means of controlling groundwater recharge on the Mesa.



5. REFERENCES

Bing Yen and Associates, Inc. (BYA) (1992), "A Geotechnical Engineering Evaluation - Big Rock Mesa, Malibu, California," dated February.

_____ (1993), "Semi-Annual Observation & Maintenance Report for the Period July to December 1992, Big Rock Mesa, Malibu, California," dated February.

_____ (1993), "Semi-Annual Observation & Maintenance Report for the Period January to July 1993, Big Rock Mesa, Malibu, California," dated September.

_____ (1994), "Annual Observation & Maintenance Report for the Period July 1993 to July 1994, Big Rock Mesa, Malibu, California," dated September.

_____ (1995), "Annual Observation & Maintenance Report for the Period July 1994 to July 1995, Big Rock Mesa, Malibu, California," dated September.

_____ (1996), "Slope Stability Evaluation - South Facing Slope Region," dated November.

_____ (1996), "Annual Observation & Maintenance Report for the Period July 1995 to July 1996, Big Rock Mesa, Malibu, California," dated September.

_____ (1997), "Annual Observation & Maintenance Report for the Period July 1996 to July 1997, Big Rock Mesa, Malibu, California," dated June.

_____ (1998), "Annual Observation & Maintenance Report for the Period July 1997 to April 1998, Big Rock Mesa, Malibu, California," dated April.

_____ (1999), "Annual Observation & Maintenance Report for the Period July 1998 to April 1999, Big Rock Mesa, Malibu, California," dated April.

_____ (2000), "Annual Observation & Maintenance Report for the Period April 1999 to June 2000, Big Rock Mesa, Malibu, California," dated August.

_____ (2001), "Annual Observation & Maintenance Report for the Period July 2000 to June 2001, Big Rock Mesa, Malibu, California," dated October.

_____ (2002), "Annual Observation & Maintenance Report for the Period July 2001 to June 2002, Big Rock Mesa, Malibu, California," dated March.

_____ (2003), "Annual Observation & Maintenance Report for the Period July 2002 to June 2003, Big Rock Mesa, Malibu, California," dated December.



Donald B. Kowalewsky (1994), "Engineering Geologic Report and Geotechnical Report for Proposed New Residence and Guest House, to Replace Previous Residence Destroyed by Fire at 20790 Rockpoint Road, Malibu, California," dated May 27.

David Taussig & Associates, Inc. (2017), "Annual Assessment District No. 98-1 (Big Rock Mesa) FY 2017-2018," dated June 26.

Fugro USA Land, Inc. (Fugro) (2018), "Annual Report, July 2016 through June 2017, Big Rock Mesa Landslide Assessment District, Malibu, California," dated March 2018.

Fugro Consultants, Inc. (Fugro) (2011), "Annual Report, July 2010 through June 2011, Big Rock Mesa Landslide Assessment District, Malibu, California," dated August 2011.

_____ (2012), "Annual Report, July 2011 through June 2012, Big Rock Mesa Landslide Assessment District, Malibu, California," dated September 2012.

_____ (2014), "Annual Report, July 2012 through June 2013, Big Rock Mesa Landslide Assessment District, Malibu, California," dated March 2014.

_____ (2015a), "Annual Report, July 2013 through June 2014, Big Rock Mesa Landslide Assessment District, Malibu, California," dated April.

_____ (2015b), "Annual Report, July 2014 through June 2015, Big Rock Mesa Landslide Assessment District, Malibu, California," dated November.

_____ (2016), "Annual Report, July 2015 through June 2016, Big Rock Mesa Landslide Assessment District, Malibu, California," dated November.

Fugro West, Inc. (Fugro) (2004), "Annual Report, July 2003 through June 2004 Malibu Road Landslide Assessment District, Malibu, California," dated November 2004.

_____ (2005), "Annual Report, July 2004 through June 2005, Big Rock Mesa Landslide Assessment District, Malibu, California," dated October 2005.

_____ (2006), "Annual Report, July 2005 through June 2006 Malibu Road Landslide Assessment District, Malibu, California," dated August 2006.

_____ (2007), "Annual Report, July 2006 through June 2007 Malibu Road Landslide Assessment District, Malibu, California," dated September 2007.

_____ (2008), "Annual Report, July 2007 through June 2008 Malibu Road Landslide Assessment District, Malibu, California," dated August 2008.




_____ (2009), "Annual Report, July 2008 through June 2009 Malibu Road Landslide Assessment District, Malibu, California," dated October 2009.

_____ (2010), "Annual Report, July 2009 through June 2010 Malibu Road Landslide Assessment District, Malibu, California," dated May 2011.



PLATES

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**



SITE LOCATION MAP
Big Rock Mesa Landslide Assessment District
Malibu, California



**BIG ROCK MESA LANDSLIDE
ASSESSMENT DISTRICT
MALIBU, CALIFORNIA**

DEWATERING FACILITIES MAP

FUGRO USA LAND, INC.
4820 McGrath St., Suite 100, Ventura, California 93003
Tel: (805) 650-7000, Fax: (805) 650-7010



- LEGEND**
- Standpipe
 - Dewatering Well (In Service)
 - Hydrauger (In Service) Color Referenced to Inferred Storm Drain Outfall
 - Storm Drain Outfall
 - Catch Basin
 - Discharge Point
 - Hydrauger
 - Approximate Limits of Primary Land Movement
 - - - Western Extension Boundary
 - Big Rock Mesa Landslide Assessment District Boundary
 - Storm Drain
 - Trees/Bush
 - Streams
 - Building
 - + Coordinate Grid: California State Plane, Zone 7, NAD 27, Feet
Vertical Datum: NAVD88 Feet




REVISIONS							
No.	DATE	DESCRIPTION	BY	No.	DATE	DESCRIPTION	BY
1	5/04/15	Discharge Pts.	TN				
2	9/24/18	Standpipes	DT				

DATE: September 24, 2015	WORK ORDER: 04.62160606	PLATE NO.:
DRAWN BY: TN	CHECKED BY: TC	APPROVED BY: TN
		2



Sources: Esri, HERE, DeLorme, USGS, Intermap, INCREMENT P, NRCan, Esri Japan, METI, Esri China (Hong Kong), Esri Korea, Esri (Thailand), MapmyIndia, NGCC, © OpenStreetMap contributors, and the GIS User Community

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**




RAINFALL GRAPH
 Big Rock Mesa Landslide Assessment District
 Malibu, California

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**




SUMMARY OF GROUNDWATER LEVELS, DEWATERING, AND RAINFALL
Big Rock Mesa Landslide Assessment District
Malibu, California

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**




TOTAL DEWATERING RATE VS. TOTAL WATER CONSUMPTION
Wells and Hydraugers(Combined)/Total Water Consumption
 Big Rock Mesa Landslide Assessment District
 Malibu, California

Groundwater Elevation (May 8, 1995)



Groundwater Elevation (May 18, 2018)



Legend

Instrumentation

- Slope Inclinator, does not Penetrate Rupture Surface
- Slope Inclinator, does Penetrate Rupture Surface

SP-16 Instrument Label and Ground Water Elevation in feet
400

Site Map Features


- Faults
- Approximate Landslide Limits
- Approximate Western Extension Limits
- Buildings



1:12,000



**GROUNDWATER ELEVATION MAP
MAY 1995 AND MAY 2018**
Big Rock Mesa Landslide
Assessment District
Malibu, California



Legend

Groundwater Elevation Change (Feet)




SP-16
-3.1
Instrument Label and
Ground Water Elevation
Change in feet


Site Map Features



1:6,000



**CHANGE IN GROUNDWATER
ELEVATION MAY 1995 TO MAY 2018**
Big Rock Mesa Landslide
Assessment District
Malibu, California



Legend

Instrumentation

SP-16
3.6
Instrument Label and Ground Water Elevation Change in feet

Site Map Features

- Faults
- Approximate Landslide Limits
- Approximate Western Extension Limits
- Buildings

Groundwater Elevation Change (Feet)

● < -30	● 0 to 5
● -30 to -15	● 5 to 10
● -15 to -10	● 10 to 15
● -10 to -5	● 15 to 20
● -5 to 0	● > 20

N

1:6,000

0 125 250 500 750 1,000 Feet

CHANGE IN GROUNDWATER ELEVATION MAY 2017 TO MAY 2018
Big Rock Mesa Landslide Assessment District
Malibu, California

N:\Projects\04_2014\04_6214_0606_City_of_Malibu_BigRockMesaOutputs\2017_8_22_AnnualReport2017\mxd\Plate-05c_WaterLevelChange_15_17.mxd, 1/21/2019, d.thornhill



**APPENDIX A
GROUNDWATER LEVEL DATA**



Big Rock Mesa: Standpipe Piezometer Information				
Piezometer ID	Surface Elev. (ft)	Depth (ft)	Perforation Interval Elevation (ft)	Installer
PCH Standpipe Piezometers				
SP-11	27	58	Unknown	Evans
SP-12	26	40	Unknown	Evans
SP-14	25	30	Unknown	Evans
SP-15	20	82	Unknown	Evans
SP-19	25	82	Unknown	Evans
SP-27A	29	94	Unknown	Evans
SP-29	27	138	Unknown	Evans
SP-30	29	128	Unknown	Evans
Bluff Standpipe Piezometers				
SP-10	295	332	Unknown	Evans
SP-28	270	358	Unknown	Evans
SP-32	233	354	Unknown	Evans
SP-34	270	382	-112 to -107	BYA
Headscarp Piezometers				
SP-26	745	346	Unknown	Conv
Central Standpipe Piezometers				
SP-9A	365	300	Unknown	Evans
SP-16	285	240	Unknown	Evans
SP-16A	285	392	Unknown	Evans
SP-17	540	192	Unknown	Evans
SP-17A	540	238	Unknown	BYA
SP-24	370	382	Unknown	Conv
SP-35	345	396	-51 to -46	BYA
SP-36	380	254	120 to 125	BYA
Western Standpipe Piezometers				
SP-20	430	326	Unknown	Conv
SP-21	660	280	Unknown	Evans
SP-22	780	332	Unknown	Conv
SP-23	860	398	Unknown	Conv
Eastern Standpipe Piezometers				
PC-1	250	160	87.5 to 90	BYA
SP-3	212	132	Unknown	Evans
SP-3A	203	246	Unknown	Evans
SP-33	208	374	Unknown	Evans

Evans - D.A. Evans

Converse - Converse Consultants

BYA - Bing Yen and Associates




PNEUMATIC PIEZOMETER INFORMATION					
Piezometer ID	Surface Elev. (ft)	Tip No.	TIP DEPTH (ft.)	INSTALL BY	STATUS
W-10**	432	230	230	BYA	No air-line, has sounder access, no data reported
W-11**	507	214	214	BYA	Air-line present, no sounder access, no data reported
W-15**	295	164	164	BYA	Air-line present, no sounder access, no data reported
PC-1	250	TIP-1	120	BYA	Functioning, reported
		TIP-2	90		0 PSI since November 2011
		TIP-3	70		Functioning, reported
		TIP-4	40		Non-Functioning, no return air flow, not reported
		TIP-5	20		Non-Functioning, no return air flow, not reported
SP-5A*	NA	TIP-1		BYA	Non-functioning - Covered by asphalt pavement
		TIP-2	NA		
		TIP-3			
SP-8A*	NA	TIP-1		BYA	Non-functioning - Covered by landslide
		TIP-2	NA		
		TIP-3			
SP-17A*	540	TIP-1	Unknown	BYA	Non-functioning, no return air flow
		TIP-2	Unknown		
		TIP-3	Unknown		
		TIP-4	Unknown		
		TIP-5	Unknown		
SP-34	270	TIP-1	381	BYA	Non-Functioning, no return air flow, not reported
		TIP-2	282		Functioning, reported
		TIP-3	182		Low PSI since installation, not reported
		TIP-4	82		Non-Functioning, no return air flow, not reported
SP-35	345	TIP-1	393	BYA	Functioning, reported
		TIP-2	293		Functioning, reported
		TIP-3	193		Non-Functioning, no return air flow, not reported
		TIP-4	98		Non-Functioning, no return air flow, not reported
SP-36	380	TIP-1	255	BYA	Functioning, reported
		TIP-2	195		Functioning, reported
		TIP-3	95		0 PSI since installation, not reported
BYA-2*	665	TIP-1	Unknown	BYA	Non-functioning, no return air flow
		TIP-2	Unknown		
		TIP-3	Unknown		
BYA-3A*	NA	TIP-1		BYA	Non-Functioning
		TIP-2			
		TIP-3	NA		
		TIP-4			
BYA-4A*	NA	TIP-1		BYA	Non-functioning, no return air flow
		TIP-2			
		TIP-3	NA		
		TIP-4			
		TIP-5			
		TIP-6			
BYA-5A*	NA	TIP-1		BYA	Non-Functioning, Paved over
		TIP-2	NA		
		TIP-3			
		TIP-4			
GEO-2 (OB-2)*	305	TIP-1		GS	Non-Functioning
		TIP-2	NA		
		TIP-3			
GEO-1*	NA	TIP-1		GS	Restricted Access (possibly malfunctioning)
		TIP-2	NA		
		TIP-3			

NOTE: * Not functioning or no longer monitored pneumatic peizometer
 ** Inactive dewatering well air-line


**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**




Piezometer I.D.	1983-84	1984-85	1985-86	1986-87	1987-88	1988-89	1989-90	1990-91	1991-92	1992-93	1993-94	1994-95	1995-96	1996-97	1997-98	1998-99	1999-00	2000-01	2001-02	2002-03	2003-04	2004-05	2005-06	2006-07	2007-08	2008-2009	2009-2010	2010-2011	2011-2012	2012-2013	2013-2014	2014-2015	2015-2016	2016-2017	2017-2018	Highest Recorded	Mean '91-'18	Stand Dev.	'17-'18 vs '97-'98	'17-'18 vs '16-'17	'17-'18 vs mean	
PCH REGION																																										
SP-11	Mean El.					5.7	5.3	4.7	4.5	5.7	5.7	5.5	5.8	5.5	5.8	6.3	5.5	4.8	5.4	5.4	5.2	5.3	5.1	5.4	4.9	4.6	5.1	8.4	7.8	4.7	4.8	5.0	5.3	5.7	5.9	Jul-16	5.5	0.9	0.1	0.2	0.4	
	Highest El.					6.4	5.8	5.5	5.0	6.0	7.4	6.9	7.5	6.7	7.3	8.1	6.5	5.5	8.3	7.0	5.7	5.8	5.9	7.6	5.9	5.2	5.6	11.8	8.8	5.0	5.1	5.9	6.1	7.2	7.2	11.8	6.7	1.5	-0.1	0.0	0.5	
SP-12	Mean El.					4.6	5.4	5.5	5.4	5.2	4.8	4.9	5.1	4.8	5.0	5.3	5.3	4.7	4.5	4.8	4.6	5.5	5.2	4.9	4.8	4.7	4.0	4.7	4.2	5.2	5.2	5.2	6.0	6.4	5.9	Feb-17	5.0	0.5	0.8	-0.5	0.8	
	Highest El.					4.6	5.4	6.0	6.0	6.0	7.2	6.1	6.3	7.4	7.0	6.4	6.5	7.4	6.4	6.4	6.4	8.3	7.2	6.4	5.8	5.7	5.1	5.3	5.2	5.5	5.8	6.2	8.8	8.8	7.8	8.81	6.6	1.0	0.8	-1.0	1.2	
SP-14	Mean El.				4.5	4.7	4.4	4.8	4.3	4.8	4.9	4.9	4.9	5.0	5.9	5.8	5.6	4.7	4.5	4.6	4.6	4.7	4.8	4.7	4.7	4.3	4.3	4.1	5.2	5.6	4.5	5.1	4.9	4.9	Feb-98	4.8	0.5	-1.0	-0.1	0.0		
	Highest El.				4.5	4.7	4.4	5.2	5.4	7.1	6.1	5.3	5.9	5.7	8.7	6.9	7.4	5.4	5.7	5.1	5.4	5.4	5.7	5.5	6.0	4.7	4.3	5.0	4.6	4.9	5.5	5.5	5.7	6.0	6.2	5.8	8.7	5.8	0.9	-2.9	-0.4	0.0
SP-15	Mean El.				11.3	8.8	10.5	9.1	7.5	10.7	13.4	12.6	15.1	14.5	12.2	12.0	11.7	11.6	11.5	11.7	10.0	11.9	11.6	11.6	11.4	8.9	8.4	7.2	7.6	5.5	5.7	8.6	10.6	10.6	8.8	Jan-97	10.5	2.4	-3.4	-1.8	-1.7	
	Highest El.				11.3	12.2	10.5	11.4	9.1	12.4	19.4	19.5	19.9	20.0	16.3	13.5	12.7	12.4	12.5	12.4	12.2	12.8	12.4	12.2	12.2	11.1	12.2	10.1	10.2	5.9	6.2	12.0	12.2	12.4	10.6	20.0	12.8	3.6	-5.7	-1.8	-2.2	
SP-19	Mean El.					3.6	3.6	3.1	4.5	4.4	4.7	4.6	4.3	4.4	4.5	3.8	3.4	3.7	3.5	3.4	3.9	3.6	3.6	3.5	3.1	3.6	3.7	3.6	3.0	3.6	3.4	3.4	3.5	3.7	Mar-95	3.7	0.5	-0.6	0.2	0.0		
	Highest El.					4.1	4.0	3.4	5.0	5.0	5.9	5.4	4.9	5.2	5.0	4.5	3.9	4.3	4.1	4.0	4.2	4.5	4.4	4.1	3.6	4.6	4.0	4.3	3.3	4.2	4.1	3.6	4.1	4.2	5.9	5.9	4.4	0.6	-1.0	0.1	-0.2	
SP-27A	Mean El.					7.1	9.1	8.8	8.7	9.3	9.4	9.7	9.5	9.5	9.7	9.6	10.1	9.2	9.0	9.5	9.3	10.2	9.7	9.5	10.0	9.5	10.0	10.0	9.7	10.5	17.1	9.7	9.1	10.0	9.9	Jun-15	9.9	1.5	0.2	-0.1	0.0	
	Highest El.					7.1	10.1	9.2	10.2	10.0	10.2	10.8	10.3	10.4	10.7	10.4	13.7	9.6	9.7	9.9	9.8	13.5	12.5	10.2	13.7	10.1	10.6	10.5	10.5	10.8	17.8	10.0	10.1	12.8	10.3	17.8	11.1	1.8	-0.4	-2.5	-0.8	
SP-29	Mean El.				19.7	20.4	19.4	18.7	18.0		19.7	20.0	19.2	19.2	19.7	18.8	18.0	18.1	17.0	16.2	16.0	18.0	17.7	16.7	16.3	15.8	15.9	16.2	15.8	16.7	15.7	14.4	13.9	14.5	14.3	Feb-05	17.0	1.8	-5.4	-0.2	-2.7	
	Highest El.				19.7	21.7	19.4	18.7	18.0		20.9	22.1	20.2	20.5	21.3	19.9	19.1	19.6	18.1	16.7	16.4	22.2	18.7	17.4	16.9	16.1	16.6	16.9	17.1	16.9	16.8	14.7	14.3	16.7	14.8	22.2	18.0	2.2	-6.6	-1.9	-3.3	
SP-30	Mean El.				7.4	7.1	6.4	7.2	6.9	7.7	7.3	7.9	8.1	9.6	8.0	8.5	9.0	9.7	11.3	12.6	12.9	13.0	13.4	13.4	14.4	15.1	15.7	16.2	15.8	16.5	16.8	13.6	13.8	16.0	16.5	Jan-17	12.2	3.4	8.4	0.5	4.3	
	Highest El.				7.4	8.0	6.4	8.0	8.0	8.0	9.3	9.6	9.4	13.3	10.2	9.6	10.1	10.8	12.6	14.3	13.4	14.3	14.1	14.2	15.3	15.5	16.4	17.2	17.0	16.8	17.1	14.6	14.7	18.6	17.9	18.6	13.4	3.2	7.7	-0.7	4.5	
Area Average	Mean El.				10.7	8.3	8.0	7.8	7.3	6.8	8.7	8.8	9.1	9.1	8.8	8.8	8.6	8.3	8.4	8.5	8.2	9.1	8.9	8.7	8.7	8.2	8.4	8.8	8.6	8.4	9.3	8.1	8.4	9.0	8.7		8.5	0.5	-0.1	-0.2	0.2	
	Highest El.				10.7	9.2	8.3	8.5	8.1	7.8	10.7	10.8	10.6	11.1	10.8	10.0	10.1	9.3	9.7	9.5	9.2	10.8	10.1	9.7	10.0	9.1	9.5	10.1	9.8	8.7	9.8	9.1	9.5	10.8	9.8		9.8	0.8	-1.0	-1.0	0.0	
Change vs Prior	Mean El.					-2.4	-0.3	-0.2	-0.5	-0.4	1.8	0.1	0.3	0.0	-0.2	0.0	-0.2	-0.3	0.1	0.2	-0.3	0.8	-0.2	-0.2	0.0	-0.5	0.2	0.4	-0.3	-0.1	0.9	-1.3	0.3	0.6	-0.2							
	Highest El.					-1.5	-1.0	0.2	-0.4	-0.4	2.9	0.1	-0.2	0.5	-0.3	-0.9	0.1	-0.7	0.4	-0.2	-0.3	1.7	-0.7	-0.4	0.3	-0.9	0.5	0.5	-0.3	-1.0	1.1	-0.7	0.3	1.4	-1.0							
BLUFF REGION																																										
SP-10	Mean El.	144.7	76.0	50.0	50.5	49.2	47.4	45.9	48.8	55.3	44.6	42.9	41.6	41.3	42.4	42.8	42.9	43.3	43.7	44.3	45.5	45.2	45.2	44.8	43.7	44.0	43.9	42.6	43.7	43.5	43.9	45.8	44.8	45.8	Dec-83	44.1	2.6	4.5	1.0	1.7		
	Highest El.	174.2	130.0	50.0	50.5	50.0	52.0	46.0	55.5	74.0	45.9	44.4	42.2	42.6	41.9	41.6	44.8	43.4	43.3	43.6	44.1	44.4	47.2	45.4	45.4	45.2	44.9	44.6	46.0	44.7	44.1	44.0	44.3	48.7	47.3	55.4	174.2	46.1	6.2	13.8	8.0	9.3
SP-28	Mean El.						36.4	33.7	37.5	33.7	33.6	33.7	33.0	32.7	31.9	32.6	33.2	33.1	33.0	32.9	34.9	34.7	33.3	33.1	32.8	33.1	32.8	35.2	32.8	32.8	33.4	33.4	33.3	33.4	33.3	33.4	Jan-12	33.2	0.7	1.5	0.1	0.1
	Highest El.						40.5	33.8	40.0	36.0	35.2	35.2	33.1	33.1	32.4	32.2	34.9	33.6	33.2	33.3	33.0	32.9	36.1	36.0	33.6	33.1	33.1	33.8	42.0	33.7	33.6	33.4	33.5	33.6	33.6	42.0	34.1	1.9	1.4	0.0	-0.5	
SP-32	Mean El.					75.3	79.1	72.6	76.1	90.1	85.9	92.5	92.5	94.9	76.5	84.2	79.7	88.2	70.1	89.9	91.1	99.9	100.2	102.3	102.4	104.4	105.1	102.3	104.8	106.4	105.6	35.0	24.0	34.3	34.8	Apr-96	84.2	24.3	-41.7	0.5	-49.4	
	Highest El.					78.2	82.3	72.8	83.2	101.0	96.2	110.2	110.2	130.9	107.4	95.3	88.4	97.0	83.6	106.0	105.8	106.7	105.9	105.9	105.8	105.8	105.9	106.9	106.9	107.1	41.3	30.3	55.0	47.1	130.9	94.5	23.8	-60.3	-7.9	-47.4		
SP-34	Mean El.															74.4	77.6	76.2	76.4	73.5	73.8	80.0	79.7	82.8	84.5	86.0	88.6	53.2	44.7	37.1	35.9	24.7	24.2	20.6	22.8	Nov-09	60.8	24.8	22.8	2.1	-38.1	
	Highest El.															85.9	79.5	77.3	77.7	74.4	74.5	82.1	81.4	83.8	86.1	88.0	94.5	64.5	48.8	48.7	36.2	26.7	27.1	22.7	23.3	94.5	64.2	24.8	23.3	0.7	-40.8	
Area Average	Mean El.	144.7	76.0	50.0	50.5	49.2	53.0	52.9	53.0	55.0	56.1	54.2	55.7	56.2	49.9	58.4	58.3	60.1	55.7	60.0	60.5	65.1	64.9	65.9	66.2	66.7	67.7	58.0	56.8	55.0	54.5	34.2	31.9	33.2	34.2		55.2	10.3	-15.7	0.9	-21.0	
	Highest El.	174.2	130.0	50.0	50.5	50.0	56.9	54.0	56.1	64.4	60.7	58.6	61.8	62.0	68.4	60.4	65.2	61.2	62.7	59.6	64.4	64.4	68.0	67.2	67.2	67.6	68.0	69.6	62.5	60.6	58.4	55.2	36.4	34.9	39.6	39.8		59.6	10.0	-20.6	0.2	-19.7
Change vs Prior	Mean El.		-68.7	-26.0	0.5	-1.3	3.8	-0.2	0.1	2.0	1.1	-1.9	1.5	0.1	0.5	-6.3	8.5	-0.1	1.8	-4.4	4.3	0.5	4.6	-0.1	0.9	0.3	0.5	0.9	-9.6	-1.2	-1.8	-0.5	-20.2	-2.4	1.4	0.9						
	Highest El.		-44.2	-80.0	0.5	-0.5	6.9	-2.9	2.1	8.3	-3.7	-2.1	3.2	0.1	6.4	-8.0	4.8	-4.0	1.5	-3.2	4.8	0.0	3.6	-0.8	0.0	0.4	0.4	1.6	-7.0	-2.0	-2.2	-3.1	-18.8	-1.5	4.8	0.2						
HEADSCARP REGION																																										
SP-26	Mean El.				541.9	540.2	538.9	535.8	532.4	527.0	532.6	543.6	543.3	547.8	547.1	549.9	551.9	549.8	550.7	550.6	549.1	550.7	553.1	554.7	553.8	552.9	551.4	551.2	552.5	551.9	551.0	551.4	552.1	551.9	552.0	552.3	Apr-01	549.1	6.2	2.5	0.3	3.2




GROUNDWATER ELEVATION DATA
Pacific Coast Highway (Western Half)
Big Rock Mesa Landslide Assessment District
Malibu, California




GROUNDWATER ELEVATION DATA
Pacific Coast Highway (Eastern Half)
Big Rock Mesa Landslide Assessment District
Malibu, California




GROUNDWATER ELEVATION DATA
Bluff Region
Big Rock Mesa Landslide Assessment District
Malibu, California




GROUNDWATER ELEVATION DATA
Eastern Mesa Region
 Big Rock Mesa Landslide Assessment District
 Malibu, California




GROUNDWATER ELEVATION DATA
Central Mesa Region
Big Rock Mesa Landslide Assessment District
Malibu, California



GROUNDWATER ELEVATION DATA
Central Mesa Region
Big Rock Mesa Landslide Assessment District
Malibu, California



GROUNDWATER ELEVATION DATA
Western Extension
Big Rock Mesa Landslide Assessment District
Malibu, California



GROUNDWATER ELEVATION DATA
Headscarp Area
Big Rock Mesa Landslide Assessment District
Malibu, California



**APPENDIX B
DEWATERING WELL DATA**

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**




SUMMARY OF DEWATERING WELL INFORMATION										
Well I.D.	DATE COMPLETED (DA Evans 1986)	TOP ELEV. (ft.)	BOTTOM ELEV. (ft.)	PUMP ELEV. (ft.)	PUMP SIZE (HP)	2017-18 PUMPING RATE (GPD)	% of TOTAL PRODUCTION	Rank	Drainage Port	COMMENT
W-1	1977	210.5	-30	14.5	1.5	1,296	3%	10	3	Producing
W-2	1955	219	41	44	1.5	2,068	5%	7	3	Producing
W-3	1973	243.5	65.5	70.5	3/4	562	1%	17	3	Producing
W-4	1973	248	-10	N/A	N/A	0	0%	25	N/A	Non-producing, casing perforations closed due to siltation (BYA 1991)
W-5	1984	280	252	N/A	N/A	0	0%	25	N/A	Capped 4/4/84 (DA Evans 1986)
W-6	1983	174	80	N/A	N/A	0	0%	25	N/A	Non-producing, static water level at bottom of casing (BYA 1991)
W-7	1983	257	171	N/A	N/A	0	0%	25	N/A	Non-producing, static water level at bottom of casing (BYA 1991)
W-8	1983	287	93	98	1	4,946	12%	4	4	Producing
W-9	1983	282	87	N/A	N/A	0	0%	25	N/A	Non-producing, static water level at bottom of casing (BYA 1991), replaced with BYA-11
W-10	1983	432	192	194	3/4	0	0%	25	N/A	Inactive, no pump
W-11	1983	507	285	292	3/4	0	0%	25	N/A	Inactive, disconnected from electrical, replaced with BYA-10
W-12	1983	375	195	N/A	N/A	0	0%	25	N/A	Non-producing, casing sheared at 185 ft.elevation (BYA 1991)
W-13	1983	361	184	193	1	976	2%	12	5	Producing
W-14	1984	283	131	N/A	N/A	0	0%	25	N/A	Non-producing, static water level at bottom of casing (BYA 1991)
W-15	1984	295	121	130	3/4	0	0%	25	N/A	Inactive, replaced with BYA-9
W-16	1984	325	107	113	3/4	5,609	13%	2	5	Producing
W-17	1984	270	41	50	3/4	2,434	6%	6	4	Producing
W-18	1984	750	179	225	3	6,356	15%	1	6	Producing
BYA-1	1990	281	-162	-128	3	1,399	3%	9	4	Producing
BYA-2	1990	665	215	242	1.5	454	1%	20	6	Producing
BYA-3	1990	510	-40	29	3	1,676	4%	8	6	Producing
BYA-4	1990	372	-68	-28	1.5	3,723	9%	5	5	Producing
BYA-5	1990	189	-231	-211	1.5	542	1%	19	1	Producing
BYA-6	1996	220	-280	-275	0.75	262	1%	22	1	Producing
BYA-7	1996	240	-120	-115	0.75	866	2%	13	2	Producing
BYA-9	1996	295	-105	-100	7.5(5)	5,241	12%	3	5	Producing
BYA-10	1996	510	210	215	1	615	1%	16	5A	Producing
BYA-11	1996	275	-125	-120	0.75	821	2%	14	5	Producing
BYA-12	1998	207	-140	-137	0.5	59	0%	23	1	Producing
BYA-13	1998	329	-14	-18	0.5	1,168	3%	11	3	Producing
BYA-14	1998	265	38	40	0.5	549	1%	18	1A	Producing
BYA-15	2002	429	340	300	1	5	0%	24	6	Producing <10 GPD
FW-1	2008	170			1	364	1%	21	1A	Producing
FW-2	2009	270	-130	-115	1.5	661	2%	15	4	Producing

Note:


- Not functioning or no longer monitored dewatering well

DEWATERING WELL INFORMATION
Big Rock Mesa Landslide Assessment District
Malibu, California


**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**




DEWATERING WELL HYDROGRAPHS
Eastern Mesa Region
Big Rock Mesa Landslide Assessment District
Malibu, California



DEWATERING WELL HYDROGRAPHS
Eastern Mesa Region
Big Rock Mesa Landslide Assessment District
Malibu, California




DEWATERING WELL HYDROGRAPHS
Eastern Mesa Region
Big Rock Mesa Landslide Assessment District
Malibu, California




DEWATERING WELL HYDROGRAPHS
Central Mesa Region
Big Rock Mesa Landslide Assessment District
Malibu, California

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**



DEWATERING WELL HYDROGRAPHS
Central Mesa Region
Big Rock Mesa Landslide Assessment District
Malibu, California



**DEWATERING WELL HYDROGRAPHS
Western Extension
Big Rock Mesa Landslide Assessment District
Malibu, California**



**APPENDIX C
HYDRAUGER DATA**

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**



SUMMARY OF HYDRAUGER INFORMATION							
HYDRAUGER ID	INSTALLED LENGTH (ft.)	OPEN LENGTH (ft.)**	Orientation/ Slope	2017-2018 Average Flow (GPD)	% OF TOTAL PRODUCTION	Rank	INSTALLED BY
H-1	700	210**	S115W / 3	16	0.1%	20	MT
HD-4	760	10	-	446	3.1%	9	D.E.
HD-5	890	530**	-	856	6.0%	6	D.E.
HD-6	980	490**	-	166	1.2%	13	D.E.
HD-7	1160	420**	-	68	0.5%	16	D.E.
HD-9	205	205**	-	452	3.2%	8	D.E.
HD-10	990	170**	-	339	2.4%	11	D.E.
HD-11	540	540**	-	77	0.5%	15	D.E.
HD-12	690	385**	-	2426	17.1%	2	D.E.
HD-15	200	200**	-	144	1.0%	14	D.E.
HD-22	568	540**	-	1022	7.2%	5	D.E.
HD-23	1280	260**	-	1499	10.6%	4	D.E.
HD-24	1030	580**	-	58	0.4%	17	D.E.
HD-25	1005	360**	-	42	0.3%	18	D.E.
HD-26	1200	410**	S37W / 1	1866	13.2%	3	D.E.
HD-28	1420	595**	-	0	--	--	D.E.
HD-29	1150	450**	-	2	0.0%	24	D.E.
HD-30	1040	10**	S13W / 7	3480	24.5%	1	D.E.
HD-33	340	340	S23W / 5	5	0.0%	23	BYA
HD-41	500	500	S18E / 3	35	0.2%	19	BYA
BYA-H8	500	345**	-	0	--	--	BYA
BYA-H10	500	10**	-	237	1.7%	12	BYA
HD-42	700	700	-	554	3.9%	7	Fugro
HD-43	700	700	-	394	2.8%	10	Fugro
H-2*	Unknown	0	-	0	--	--	MT
H-3a*	Unknown	0	-	0	--	--	MT
H-3b*	Unknown	0	-	0	--	--	MT
H-3c*	Unknown	0	-	0	--	--	MT
H-4	680	115**	-	0	--	--	MT
H-5a*	Unknown	0	-	0	--	--	MT
H-5b*	Unknown	0	-	0	--	--	MT
H-6a*	100	96	-	0	--	--	CT
H-6b*	100	96	-	0	--	--	CT
H-7a*	100	100	-	0	--	--	CT
H-7b*	100	96	-	0	--	--	CT
H-7c*	50	0	-	0	--	--	CT
H-8*	Unknown	0	-	0	--	--	CT
HD-1*	350	340**	-	0	--	--	D.E.
HD-2a*	70	33	-	0	--	--	D.E.
HD-2b*	Unknown	0	-	0	--	--	D.E.
HD-2c*	460	0	-	0	--	--	D.E.
HD-3	560	90**	-	0	--	--	D.E.
HD-8*	530	170**	-	0	--	--	D.E.
HD-13*	650	14	-	0	--	--	D.E.
HD-14*	130	130**	-	0	--	--	D.E.
HD-16	575	575**	-	0	--	--	D.E.
HD-17*	750	176	-	0	--	--	D.E.
HD-18*	870	285	-	0	--	--	D.E.
HD-19*	1000	182	-	0	--	--	D.E.
HD-20*	1000	446	-	0	--	--	D.E.
HD-21*	1560	147	-	0	--	--	D.E.
HD-27*	700	327	-	0	--	--	D.E.
HD-31*	140	113	-	0	--	--	D.E.
HD-32*	835	700**	-	0	--	--	D.E.
HD-34	150	150	S40W / 10	0	--	--	BYA
HD-35*	40	40	-	0	--	--	BYA
HD-36*	150	150	-	0	--	--	BYA
HD-37*	430	50	-	0	--	--	BYA
HD-38A*	140	140	S23W / 5	0	--	--	BYA
HD-38B*	140	140	S18W / 6	0	--	--	BYA
HD-39	400	400	S15E / 5	0	--	--	BYA
HD-40*	595	595	S25W / 6	0	--	--	BYA
BYA-6a	350	20**	-	8	0.1%	22	BYA
BYA-6b	60	60	-	9	0.1%	21	BYA
BYA-7	400	375**	-	0	--	--	BYA
BYA-H9*	550	550**	-	0	--	--	BYA
BYA-H11*	450	400**	S7E / 3	0	--	--	BYA



* Not functioning or no longer monitored hydrauger

** Open Length is Measured on 10-1997 by BYA

Installed by: MT = Moore & Taber; CT = Caltrans; D.E. = D.A. Evans; BYA = Bing Yen & Associates



SUMMARY OF HYDRAUGER INFORMATION
Big Rock Mesa Landside Assessment District
Malibu, California

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**





DISCHARGE RATE FOR HYDRAUGERS
Eastern Mesa Region
 Big Rock Mesa Landslide Assessment District
 Malibu, California

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**





DISCHARGE RATE FOR HYDRAUGERS
Eastern Mesa Region
 Big Rock Mesa Landslide Assessment District
 Malibu, California

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**





DISCHARGE RATE FOR HYDRAUGERS
Central Mesa Region
 Big Rock Mesa Landslide Assessment District
 Malibu, California

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**



DISCHARGE RATE FOR HYDRAUGERS
Central Mesa Region
 Big Rock Mesa Landslide Assessment District
 Malibu, California

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**




**DISCHARGE RATE FOR HYDROGRAPHS
 Western Extension
 Big Rock Mesa Landslide Assessment District
 Malibu, California**



**APPENDIX D
SLOPE INCLINOMETER PLOT/DATA**

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-11
PCH REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-11
PCH REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-11

PCH REGION

PLATE D2-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-11

PCH REGION

PLATE D2-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-12
 PCH REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**


Fugro West, Inc. - Ventura, CA



BIG ROCK MESA, Inclinometer SP-12
 PCH REGION

PLATE D3-2

Sets marked * include zero shift and/or rotation corrections.




BIG ROCK MESA, Inclinator SP-12

PCH REGION

PLATE D3-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-12

PCH REGION

PLATE D3-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-14
PCH REGION**

Sets marked * include zero shift and/or rotation corrections.


**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA



BIG ROCK MESA, Inclinometer SP-14
 PCH REGION


Sets marked * include zero shift and/or rotation corrections.



BIG ROCK MESA, Inclinometer SP-14

PCH REGION


PLATE D4-3



BIG ROCK MESA, Inclinator SP-14

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-15
 PCH REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-15
 PCH REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-15

PCH REGION

PLATE D5-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-15

PCH REGION

PLATE D5-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-19
 PCH REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**


Fugro West, Inc. - Ventura, CA



**BIG ROCK MESA, Inclinometer SP-19
 PCH REGION**

PLATE D6-2


Sets marked * include zero shift and/or rotation corrections.



BIG ROCK MESA, Inclinator SP-19

PCH REGION

PLATE D6-3




BIG ROCK MESA, Inclinator SP-19

PCH REGION

PLATE D6-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-27A
 PCH REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinator SP-27A
 PCH REGION**

PLATE D7-2

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**


Fugro West, Inc. - Ventura, CA



BIG ROCK MESA, Inclinometer SP-27A

PCH REGION


PLATE D7-3



BIG ROCK MESA, Inclinator SP-27A

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-29
PCH REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-29
 PCH REGION

PLATE D8-2

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-29

PCH REGION

PLATE D8-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-29

PCH REGION

PLATE D8-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Incliner SP-30
PCH REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-30
PCH REGION

PLATE D9-2

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-30

PCH REGION

PLATE D9-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-30

PCH REGION

PLATE D9-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-10
 BLUFF REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-10
 BLUFF REGION

PLATE D10-2

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**


Fugro USA Land, Inc. - Ventura, CA



BIG ROCK MESA, Inclinometer SP-10

BLUFF REGION

PLATE D10-3




BIG ROCK MESA, Inclinometer SP-10

BLUFF REGION

PLATE D10-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro Consultants, Inc. - Ventura, CA



past movement at 245 feet

**BIG ROCK MESA, Inclinometer SP-28
 BLUFF REGION**


past movement at 245 feet

Sets marked * include zero shift and/or rotation corrections.

PLATE D11-1

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro Consultants, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-28
 BLUFF REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro Consultants, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-28

BLUFF REGION

PLATE D11-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro Consultants, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-28

BLUFF REGION

PLATE D11-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-32
 BLUFF REGION**

PLATE D12-1

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-32
 BLUFF REGION**

PLATE D12-2

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-32

BLUFF REGION

PLATE D12-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-32

BLUFF REGION

PLATE D12-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinator PC-1
 EASTERN REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer PC-1
 EASTERN REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer PC-1

EASTERN REGION

PLATE D13-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer PC-1

EASTERN REGION

PLATE D13-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinerometer SP-3
 EASTERN REGION**

Sets marked * include zero shift and/or rotation corrections.


**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA



**BIG ROCK MESA, Inclinometer SP-3
 EASTERN REGION**

Sets marked * include zero shift and/or rotation corrections.




BIG ROCK MESA, Inclinometer SP-3

EASTERN REGION

PLATE D14-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-3

EASTERN REGION

PLATE D14-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-3A
 EASTERN REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-3A
 EASTERN REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-3A

EASTERN REGION

PLATE D15-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-3A

EASTERN REGION

PLATE D15-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-33
 EASTERN REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-33
 EASTERN REGION

PLATE D16-2

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-33

EASTERN REGION

PLATE D16-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-33

EASTERN REGION

PLATE D16-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Incliner SP-9A
 CENTRAL REGION**

Sets marked * include zero shift and/or rotation corrections.


**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-9A
 CENTRAL REGION

Sets marked * include zero shift and/or rotation corrections.



BIG ROCK MESA, Inclinometer SP-9A

CENTRAL REGION




BIG ROCK MESA, Inclinometer SP-9A

CENTRAL REGION

PLATE D17-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-16A
 CENTRAL REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-16A
 CENTRAL REGION

PLATE D18-2

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-16A

CENTRAL REGION

PLATE D18-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-16A

CENTRAL REGION

PLATE D18-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BRM, Inclinator SP-17B

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BRM, Inclinometer SP-17B

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**


Fugro USA Land, Inc. - Ventura, CA



BRM, Inclinator SP-17B

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**


Fugro USA Land, Inc. - Ventura, CA



BRM, Inclinator SP-17B

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-24
 CENTRAL REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**


Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-24
 CENTRAL REGION

PLATE D20-2

Sets marked * include zero shift and/or rotation corrections.



BIG ROCK MESA, Inclinometer SP-24




BIG ROCK MESA, Inclinometer SP-24

CENTRAL REGION

PLATE D20-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-34
 CENTRAL REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-34
 CENTRAL REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-34

CENTRAL REGION

PLATE D21-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-34

CENTRAL REGION

PLATE D21-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-35
 CENTRAL REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-35
CENTRAL REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-35

CENTRAL REGION

PLATE D22-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-35

CENTRAL REGION

PLATE D22-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-36
 CENTRAL REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-36
 CENTRAL REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-36

CENTRAL REGION

PLATE D23-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-36

CENTRAL REGION

PLATE D23-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-20
 WESTERN REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-20
 WESTERN REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-20

WESTERN REGION

PLATE D24-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-20

WESTERN REGION

PLATE D24-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinator SP-21
WESTERN REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-21
 WESTERN REGION**

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-21

WESTERN REGION

PLATE D25-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-21

WESTERN REGION

PLATE D25-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




**BIG ROCK MESA, Inclinometer SP-22
 WESTERN REGION**

Sets marked * include zero shift and/or rotation corrections.


**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA



**BIG ROCK MESA, Inclinator SP-22
 WESTERN REGION**

Sets marked * include zero shift and/or rotation corrections.




BIG ROCK MESA, Inclinometer SP-22

WESTERN REGION

PLATE D26-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro West, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-22

WESTERN REGION

PLATE D26-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinerometer SP-23
 WESTERN REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinerometer SP-23
 WESTERN REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-23

WESTERN REGION

PLATE D27-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-23

WESTERN REGION

PLATE D27-4

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-26
 HEADSCARP REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
 FY17-18 ANNUAL REPORT
 MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinometer SP-26
 HEADSCARP REGION

Sets marked * include zero shift and/or rotation corrections.

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA




BIG ROCK MESA, Inclinator SP-26

HEADSCARP REGION

PLATE D28-3

**BIG ROCK MESA LANDSLIDE ASSESSMENT DISTRICT
FY17-18 ANNUAL REPORT
MALIBU, CALIFORNIA**

Fugro USA Land, Inc. - Ventura, CA



BIG ROCK MESA, Inclinometer SP-26

HEADSCARP REGION

PLATE D28-4



**APPENDIX E
WATER QUALITY TESTING**

Date Sampled	INORGANIC NON-METALS (Aqueous Matrix)																				
	Sample Point	pH (Field Measured)	Temperature	Biochemical Oxygen Demand	Surfactants (MBAS)	Oil & Grease	Settleable Solids	Sulfides	Phenols	Residual Chlorine (Field Measured)	Total Suspended Solids	Turbidity	TPH Diesel	TPH Motor Oil	Bis(2-Ethylhexyl) Phthalate	Zinc	Total Coliform	Fecal Coliform	Fecal/Total Coliform >0.1?	Enterococcus	Acute Toxicity**
Units:			°F	mg/L	mg/L	mg/L	mL/L	mg/L	mg/L	mg/L	mg/L	NTU	µg/L	µg/L	µg/L	µg/L	MPN/100ml	MPN/100ml		MPN/100ml	% Survival
Discharges to M-001 (Outfall/Port #1a)																					
7/6/2017	M-001	8.58	67.8	1.8	ND	ND	ND	ND	ND	0.14	ND	0.56	ND	ND	ND	45 J	4600	2	No	25.3	--
7/13/2017	M-001	8.58	68.7	--	--	--	--	--	--	0.07	--	--	--	--	--	--	--	--	--	--	--
7/18/2017	M-001	8.50	68.4	--	--	--	--	--	--	0.06	--	--	--	--	--	--	--	--	--	--	--
7/25/2017	M-001	8.56	73.9	--	--	--	--	--	--	0.05	--	--	--	--	--	--	--	--	--	--	--
8/7/2017	M-001	8.53	73.6	ND	0.025 J	ND	ND	ND	ND	0.04	1.6	0.38	ND	ND	ND	34 J	790	130	Yes	45.9	--
9/6/2017	M-001	8.58	72.3	1.7	0.022 J	ND	ND	ND	ND	--	1.1	0.33	ND	ND	ND	18 J	170	<1.8	No	4.1	--
9/14/2017	M-001	8.34	--	--	--	--	--	--	--	0.00	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-002 (Outfall/Port #1)																					
7/6/2017	M-002	8.33	69.4	1.6	ND	ND	ND	ND	ND	0.05	ND	0.21	ND	ND	ND	ND	2300	4.5	No	27.8	--
8/7/2017	M-002	8.23	72.3	ND	0.019 J	ND	ND	ND	ND	0.01	0.89	0.18	ND	ND	ND	ND	330	<1.8	No	19.7	--
9/6/2017	M-002	8.25	72.7	ND	0.025 J	ND	ND	ND	ND	--	ND	0.26	ND	ND	ND	ND	790	<1.8	No	13.5	--
9/14/2017	M-002	7.94	--	--	--	--	--	--	--	0.00	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-003 (Outfall/Port #2)																					
7/6/2017	HD-41	7.20	72.7	ND	ND	ND	ND	ND	ND	0.00	ND	0.18	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
8/7/2017	HD-41	6.76	70.3	ND	ND	ND	ND	ND	ND	0.00	ND	0.21	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
9/6/2017	HD-41	6.94	78.3	ND	ND	ND	ND	ND	ND	--	ND	0.42	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
9/14/2017	HD-41	7.02	--	--	--	--	--	--	--	0.05	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-004 (Outfall/Port #3)																					
7/6/2017	M-004	8.26	71.4	ND	ND	ND	ND	ND	ND	0.06	ND	0.21	ND	ND	ND	30 J	7000	4600	Yes	307.6	--
7/6/2017	Duplicate	8.26	71.4	1.6	.031 J	ND	ND	ND	ND	0.06	ND	0.22	ND	ND	ND	31 J	17000	7900	Yes	325.5	--
8/7/2017	M-004	7.96	73.2	ND	ND	ND	ND	ND	ND	0.07	ND	0.25	ND	ND	ND	31 J	4900	130	No	80.1	--
9/6/2017	M-004	7.97	75.7	1.7	.031 J	ND	ND	ND	ND	--	0.67	0.68	ND	ND	ND	43 J	24000	3300	Yes	387.3	--
9/14/2017	M-004	7.82	--	--	--	--	--	--	--	0.07	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-005 (Outfall/Port #4)																					
7/6/2017	M-005	8.31	72.9	ND	ND	ND	ND	ND	ND	0.06	1.7	0.24	ND	ND	ND	ND	35000	1700	No	>2420	--
8/7/2017	M-005	8.08	75.4	ND	0.025 J	ND	ND	ND	ND	0.02	ND	0.53	ND	ND	ND	15 J	160000	170	No	>2420	--
8/7/2017	Duplicate	8.08	75.4	ND	0.076 J	ND	ND	ND	ND	0.02	1.1	0.54	ND	ND	ND	12 J	35000	490	No	>2420	--
9/6/2017	M-005	8.25	73.8	1.7	ND	ND	ND	ND	ND	--	0.89	0.36	ND	ND	ND	62	7900	790	No	686.7	--
9/14/2017	M-005	8.03	--	--	--	--	--	--	--	0.09	--	--	--	--	--	--	--	--	--	--	--
9/19/2017	M-005	8.07	71.1	--	--	--	--	--	--	0.16	--	--	--	--	--	62	--	--	--	--	--
9/27/2017	M-005	8.08	73.8	--	--	--	--	--	--	--	--	--	--	--	--	54	--	--	--	--	--
Discharges to M-006 (Outfall/Port #5)																					
7/6/2017	M-006	8.35	73.2	1.6	ND	ND	ND	ND	ND	0.05	1.1	0.18	ND	ND	ND	ND	1100	4.5	No	21.1	--
8/7/2017	M-006	8.20	75.0	ND	ND	ND	ND	ND	.02 J	0.03	0.67	0.20	ND	ND	ND	ND	1400	130	No	151.5	--
9/6/2017	M-006	8.23	79.3	1.8	ND	ND	ND	ND	ND	--	0.89	0.40	ND	ND	ND	ND	940	23	No	15.6	--
9/14/2017	M-006	8.01	--	--	--	--	--	--	--	0.00	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-007 (Outfall/Port #5a)																					
7/6/2017	M-007	8.17	72.7	2.1	ND A07	ND	ND	ND	ND	0.09	ND	0.17	ND	ND	ND	ND	11	<1.8	No	9.6	--
8/7/2017	M-007	8.13	75.7	ND	ND	ND	ND	ND	ND	0.01	ND	0.17	ND	ND	ND	ND	1700	2	No	4	--
9/6/2017	M-007	8.15	75.6	1.9	ND	ND	ND	ND	ND	--	0.67	0.22	ND	ND	ND	ND	170	6.8	No	4.1	--
9/14/2017	M-007	7.93	--	--	--	--	--	--	--	0.00	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-008 (Outfall/Port #5)																					
7/6/2017	M-008	8.42	72.9	1.6	ND	ND	ND	ND	ND	0.00	7.7	2.0	ND	ND	ND	15 J	2200	46	No	>2420	--
8/7/2017	M-008	8.29	75.7	ND	0.025 J	ND	ND	ND	0.01 J	0.04	0.78	0.38	ND	ND	ND	ND	790	6.8	No	248.9	--
9/6/2017	M-008	8.37	75.2	2.0	ND	ND	ND	ND	ND	--	0.67	0.98	ND	ND	ND	ND	1100	49	No	1011.2	--
9/6/2017	Duplicate	8.37	75.2	ND	ND	ND	ND	ND	ND	--	ND	1.0 S05	ND	ND	ND	ND	700	33	No	>2420	--
9/14/2017	M-008	8.17	--	--	--	--	--	--	--	0.31	--	--	--	--	--	--	--	--	--	--	--
9/19/2017	M-008	8.19	69.6	--	--	--	--	--	--	0.18	--	--	--	--	--	--	--	--	--	--	--
9/27/2017	M-008	8.24	70.3	--	--	--	--	--	--	0.22	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-009 (Outfall/Port #5)																					
7/6/2017	M-009	7.99	79.5	ND	.025 J	ND	ND	ND	ND	0.03	ND	0.16	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
8/7/2017	M-009	8.12	72.5	ND	ND	ND	ND	ND	ND	0.00	1.3	0.16	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
9/6/2017	M-009	7.95	78.4	1.5	ND	ND	ND	ND	ND	--	0.56	0.20	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
9/14/2017	M-009	7.80	--	--	--	--	--	--	--	0.06	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-010 (Outfall/Port #9)																					
7/6/2017	M-010	8.32	71.8	3.7	ND	ND	ND	ND	ND	0.05	ND	0.32	ND	ND	ND	ND	49	<1.8	No	4.1	--
8/7/2017	M-010	8.48	76.6	ND	ND	ND	0.10	ND	ND	0.01	170	0.24	ND	ND	ND	ND	2300	<1.8	No	<1	--
8/23/2017	M-010	8.17	75.0	--	--	--	--	--	--	--	8.2	--	--	--	--	--	--	--	--	--	--
8/30/2017	M-010	8.18	73.4	--	--	--	--	--	--	--	ND	--	--	--	--	--	--	--	--	--	--
9/6/2017	M-010	8.25	74.7	3.1	.031 J	ND	ND	ND	ND	--	ND	1.0	ND	ND	ND	ND	14	<1.8	No	16.3	--
9/14/2017	M-010	8.05	--	--	--	--	--	--	--	0.05	--	--	--	--	--	--	--	--	--	--	--
Effluent Limit (Daily Max.)																					
Effluent Limit (Daily Max. if Fecal/Total Coliform > 0.1)																					
Effluent Limit (Monthly Avg.)																					

- = Not tested for
- = No established limit.
- ** = Acute Toxicity samples were collected on 1/21/15
- ND = none detected above laboratory
- NR = No reading taken
- J = Laboratory estimated value, below PQL and above the MDL.
- A = Laboratory PQLs were raised due to sample dilution caused by high analyte concentration or matrix interference.
- B = Indicates laboratory measurement.
- A01 = Detection and quantitation limits were raised due to sample dilution
- A52 = Chromatogram not typical of diesel
- A57 = Chromatogram not typical of motor oil
- A07 = Detection and quantitation limits were raised due to sample dilution caused by high analyte concentration or matrix interference.
- D = Chromatogram not typical of motor oil
- 1 = Chlorine test repeated after flow appeared to increase
- 2 = Area of coalescence that discharges through M-007

	0.12 Exceedance of effluent limit.
	Waiting for data
	Exceedance Sampling Needed

**SUMMARY OF WATER QUALITY MONITORING DATA
Third Quarter (Jul.-Sep.) 2017**

Date Sampled	INORGANIC NON-METALS (Aqueous Matrix)																				
	Sample Point	pH (Field Measured)	Temperature	Biochemical Oxygen Demand	Surfactants (MBAS)	Oil & Grease	Settleable Solids	Sulfides	Phenols	Residual Chlorine (Field Measured)	Total Suspended Solids	Turbidity	TPH Diesel	TPH Motor Oil	Bis(2-Ethylhexyl) Phthalate	Zinc	Total Coliform	Fecal Coliform	Fecal/Total Coliform >0.1?	Enterococcus	Acute Toxicity**
Units:			°F	mg/L	mg/L	mg/L	mL/L	mg/L	mg/L	mg/L	mg/L	NTU	µg/L	µg/L	µg/L	µg/L	MPN/100ml	MPN/100ml		MPN/100ml	% Survival
Discharges to M-001 (Outfall/Port #1a)																					
10/5/2017	M-001	8.37	67.8	1.7	0.018 J	ND	0.20	ND	ND	0.07	29	1.8	ND	ND	ND	27 J	3300	1700	Yes	1986.3	--
10/19/2017	M-001	8.63	71.2	--	--	--	ND	--	--	--	--	--	--	--	--	--	--	--	--	--	--
10/24/2017	M-001	8.42	77.2	--	--	--	ND	--	--	--	--	--	--	--	--	--	--	--	--	--	--
11/1/2017	M-001	8.49	71.2	ND	0.029 J	ND	ND	ND	ND	0.04	ND	0.28	ND	ND	ND	15 J	3300	230	No	272.3	100
11/9/2017	M-001	8.42	69.1	--	--	--	ND	--	--	--	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-002 (Outfall/Port #1)																					
10/5/2017	M-002	8.12	69.3	1.8	0.018 J	ND	5.0	ND	ND	0.02	55	2.0	ND	ND	ND	790	110	Yes	75.9	--	
10/19/2017	M-002	8.25	70.2	--	--	--	ND	--	--	--	ND	--	--	--	--	--	--	--	--	--	--
10/24/2017	M-002	8.06	82.0	--	--	--	ND	--	--	--	ND	--	--	--	--	--	--	--	--	--	--
11/1/2017	M-002	8.13	71.1	ND	ND	ND	ND	ND	ND	0.00	0.96	0.21	ND	ND	ND	130	<1.8	No	2	100	
11/9/2017	M-002	7.81	69.8	--	--	--	2.2	--	--	--	1.0	--	--	--	--	--	--	--	--	--	--
12/4/2017	M-002	8.18	63.5	1.8	ND A07	ND	ND	ND	ND	0.03	0.56	0.52	ND	ND	ND	790	2	No	2	--	
12/28/2017	M-002	8.17	66.6	--	--	--	ND	--	--	--	--	--	--	--	--	--	--	--	--	--	--
Discharges to M-003 (Outfall/Port #2)																					
12/4/2017	HD-41	7.25	66.7	2.1	ND	ND	ND	ND	ND	0.00	1.2	0.29	ND	ND	ND	13 J	<1.8	<1.8	--	1	--
Discharges to M-004 (Outfall/Port #3)																					
10/5/2017	M-004	7.86	71.4	2.5	0.070 J	ND	ND	ND	ND	0.08	1.1	0.36	ND	ND	ND	37 J	54000	13000	Yes	816.4	--
11/1/2017	M-004	8.08	69.3	ND	0.024 J	ND	ND	ND	ND	0.06	1.4	0.23	ND	ND	ND	41 J	4900	170	No	307.6	100
12/4/2017	M-004	7.97	68.0	ND	ND	ND	ND	ND	ND	0.14	1.1	0.47	ND	ND	ND	33 J	330	4.5	No	48	--
Discharges to M-005 (Outfall/Port #4)																					
10/5/2017	M-005	8.19	72.1	3.2	0.10	ND	ND	ND	ND	0.01	1.7	0.36	ND	ND	ND	54	7900	2300	Yes	184.2	--
10/11/2017	M-005	8.04	70.0	--	--	--	--	--	--	--	--	--	--	--	--	44 J	--	--	--	--	--
10/19/2017	M-005	8.17	73.9	--	--	--	--	--	--	--	--	--	--	--	--	66	--	--	--	--	--
10/24/2017	M-005	8.17	75.4	--	--	--	--	--	--	--	--	--	--	--	--	97	--	--	--	--	--
11/1/2017	M-005	8.04	69.4	2.9	0.36	ND	ND	ND	ND	0.00	2.2	0.80	69 A52	ND	ND	50	54000	460	No	>2420	100
11/9/2017	M-005	8.12	71.2	--	--	--	--	--	--	--	--	--	--	--	--	35 J	--	--	--	--	--
11/14/2017	M-005	8.27	74.7	--	--	--	--	--	--	--	--	--	--	--	--	36 J	--	--	--	--	--
11/21/2017	M-005	8.16	72.3	--	--	--	--	--	--	--	--	--	--	--	--	46 J	--	--	--	--	--
11/30/2017	M-005	8.01	73.9	--	--	--	--	--	--	--	--	--	--	--	--	59	--	--	--	--	--
12/4/2017	M-005	8.17	63.5	2.3	ND	ND	ND	ND	ND	0.03	ND	0.51	ND	ND	ND	38 J	54000	4.5	No	579.4	--
12/14/2017	M-005	8.17	69.4	--	--	--	--	--	--	--	--	--	--	--	--	38 J	--	--	--	--	--
12/21/2017	M-005	8.13	64.2	--	--	--	--	--	--	--	--	--	--	--	--	33 J	--	--	--	--	--
12/28/2017	M-005	8.18	66.9	--	--	--	--	--	--	--	--	--	--	--	--	41 J	--	--	--	--	--
Discharges to M-006 (Outfall/Port #5)																					
10/5/2017	M-006	8.20	73.0	ND	ND	ND	ND	ND	ND	0.05	5.1	0.23	ND	ND	ND	330	33	No	61.3	--	
Duplicate	M-006	8.20	73.0	ND	ND A07	ND	ND	ND	ND	0.05	ND	0.30	ND	ND	ND	1700	63	No	63.1	--	
11/1/2017	M-006	8.14	70.5	ND	0.029 J	ND	ND	ND	ND	0.00	1.2	0.27	ND	ND	ND	7900	330	No	378.4	100	
12/4/2017	M-006	8.17	66.7	ND	ND	ND	ND	ND	ND	0.03	ND	0.28	ND	ND	ND	790	2	--	4.1	--	
Discharges to M-007 (Outfall/Port #5a)																					
10/5/2017	M-007	8.02	72.0	2.8	0.057 J	ND	ND	ND	ND	0.04	3.4	0.56	ND	ND	ND	1300	1300	Yes	36.4	--	
11/1/2017	M-007	8.07	70.7	ND	0.024 J	ND	ND	ND	ND	0.09	ND	0.18	ND	ND	ND	790	<1.8	No	35.9	100	
Duplicate	M-007	8.07	70.7	ND	ND	ND	ND	ND	ND	0.09	ND	0.18	ND	ND	ND	170	4.5	No	28.8	100	
12/4/2017	M-007	8.10	65.8	2.9	ND	ND	ND	ND	ND	0.01	ND	0.44	ND	ND	ND	2300	1300	Yes	13.2	--	
Discharges to M-008 (Outfall/Port #5)																					
10/5/2017	M-008	8.27	72.0	ND	ND	ND	ND	ND	ND	0.04	ND	0.62	ND	ND	ND	9.7 J	700	140	Yes	23	--
10/11/2017	M-008	7.95	67.8	--	--	--	--	--	--	0.12	--	--	--	--	--	--	--	--	--	--	--
10/19/2017	M-008	8.48	72.1	--	--	--	--	--	--	0.22	--	--	--	--	--	--	--	--	--	--	--
10/24/2017	M-008	8.14	71.2	--	--	--	--	--	--	0.17	--	--	--	--	--	--	--	--	--	--	--
11/1/2017	M-008	8.20	68.4	ND	ND	ND	ND	ND	ND	0.21	1.6	0.50	ND	ND	ND	2800	79	No	2419.6	100	
11/9/2017	M-008	8.20	68.4	--	--	--	--	--	--	0.18	--	--	--	--	--	--	--	--	--	--	--
11/14/2017	M-008	8.41	78.1	--	--	--	--	--	--	0.24	--	--	--	--	--	--	--	--	--	--	--
11/21/2017	M-008	8.18	69.4	--	--	--	--	--	--	0.16	--	--	--	--	--	--	--	--	--	--	--
11/30/2017	M-008	8.04	72.3	--	--	--	--	--	--	0.11	--	--	--	--	--	--	--	--	--	--	--
12/4/2017	M-008	8.39	65.8	ND	ND	ND	ND	ND	ND	0.05	1.3	0.48	ND	ND	ND	100	35000	24000	Yes	686.7	--
Duplicate	M-008	8.39	65.8	2.3	ND	ND	ND	ND	ND	0.05	3.2	5.7	ND	ND	ND	30 J	4600	2200	Yes	83.9	--
12/14/2017	M-008	8.31	69.9	--	--	--	--	--	--	0.08	--	--	--	--	--	31 J	--	--	--	--	--
12/21/2017	M-008	8.28	60.1	--	--	--	--	--	--	0.15	--	--	--	--	--	39 J	--	--	--	--	--
12/28/2017	M-008	8.27	62.2	--	--	--	--	--	--	0.17	--	--	--	--	--	47 J	--	--	--	--	--
Discharges to M-009 (Outfall/Port #5)																					
10/5/2017	M-009	7.85	77.5	ND	ND	ND	ND	ND	ND	0.00	2.0	0.24	ND	ND	ND	280	<1.8	<1.8	N/A	<1	--
10/19/2017	M-009	7.80	75.2	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
10/24/2017	M-009	7.82	76.5	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
11/1/2017	M-009	8.00	70.7	ND	0.021 J	ND	ND	ND	ND	0.28	7.9	1.0	ND	ND	ND	<1.8	<1.8	N/A	<1	100	
11/9/2017	M-009	7.93	73.6	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
11/14/2017	M-009	7.88	75.6	--	--	--	--	--	--	0.00	--	--	--	--	--	--	--	--	--	--	--
11/21/2017	M-009	7.90	76.1	--	--	--	--	--	--	0.00	--	--	--	--	--	--	--	--	--	--	--
11/30/2017	M-009	7.79	73.2	--	--	--	--	--	--	0.01	--	--	--	--	--	--	--	--	--	--	--
12/4/2017	M-009	7.84	75.0	1.6	ND	ND	ND	ND	ND	0.00	1.2	0.22	ND	ND	ND	2	<1.8	<1.8	No	<1	--
Discharges to M-010 (Outfall/Port #9)																					
10/5/2017	M-010	8.20	70.9	1.5	ND	ND	ND	ND	ND	0.00	1.4	0.62	ND	ND	ND	16 J	13000	7.8	No	77.1	--
11/1/2017	M-010	8.07	71.8	1.8	ND A07	ND	ND	ND	ND	0.00	ND	0.25	ND	ND	ND	130	<1.8	<1.8	No	1	100
12/4/2017	M-010	8.20	66.0	2.9	ND	ND	ND	ND	ND	0.00	0.56	0.42	ND	ND	ND	230	2	No	<1	--	
Effluent Limit (Daily Max.)																					
Effluent Limit (Daily Max. if Fecal/Total Coliform > 0.1)																					
Effluent Limit (Monthly Avg.)																					

- = Not tested for.
- = No established limit.
- ** = Acute Toxicity samples were collected on 11/1/2017.
- ND = none detected above laboratory reporting limits.
- NR = No reading taken.
- J = Laboratory estimated value, below PQL and

Date Sampled	INORGANIC NON-METALS (Aqueous Matrix)																				
	Sample Point	pH (Field Measured)	Temperature	Biochemical Oxygen Demand	Surfactants (MBAS)	Oil & Grease	Settleable Solids	Sulfides	Phenols	Residual Chlorine (Field Measured)	Total Suspended Solids	Turbidity	TPH Diesel	TPH Motor Oil	Bis(2-Ethylhexyl) Phthalate	Zinc	Total Coliform	Fecal Coliform	Fecal/Total Coliform >0.1?	Enterococcus	Acute Toxicity**
Units:			°F	mg/L	mg/L	mg/L	mL/L	mg/L	mg/L	mg/L	mg/L	NTU	µg/L	µg/L	µg/L	µg/L	MPN/100ml	MPN/100ml		MPN/100ml	% Survival
Discharges to M-001 (Outfall/Port #1a)																					
1/11/2018	M-001	8.48	65.8	2.1	0.047 J	ND	ND	ND	.01 J	0.00	0.78	0.57	ND	ND	ND	19 J	35000	330	No	770.1	--
2/13/2018	M-001	8.51	66.0	1.7	0.024 J	ND	ND	ND	ND	0.00	ND	0.49	ND	ND	ND	24 J	2300	4.5	No	35.9	--
Duplicate	M-001	8.51	66.0	1.6	0.018 J	ND	ND	ND	ND	0.00	1.5	0.35	ND	ND	ND	11 J	--	--	--	--	--
3/6/2018	M-001	8.41	60.3	2.0	ND	ND	ND	ND	ND	0.05	0.60	0.35	17 J	ND	ND	17 J	2800	130	No	130.1	--
Discharges to M-002 (Outfall/Port #1)																					
1/5/2018	M-002	8.24	71.1	--	--	ND	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--
1/11/2018	M-002	8.19	70.5	ND	ND	ND	ND	ND	ND	0.00	ND	0.52	ND	ND	ND	ND	1300	4.5	No	35	--
2/13/2018	M-002	8.21	64.2	4.4	ND	ND	ND	ND	ND	0.07	0.75	0.23	ND	ND	ND	ND	1100	<1.8	No	<1	--
3/6/2018	M-002	8.12	61.2	ND	0.021 J	ND	ND	ND	0.12	0.06	ND	0.24	ND	ND	ND	ND	3300	7.8	No	18.3	--
Duplicate	M-002	8.12	61.2	ND	0.024 J	ND	ND	ND	0.049 J	0.06	ND	0.24	ND	ND	ND	140	2800	11	No	13.4	--
3/15/2018	M-002	8.08	67.8	--	--	--	--	--	--	0.00	--	--	--	--	--	18 J	--	--	--	--	--
3/23/2018	M-002	8.41	61.5	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
3/27/2018	M-002	9.40	70.7	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
Discharges to M-003 (Outfall/Port #2)																					
1/11/2018	HD-41	7.28	72.1	ND	0.026 J	ND	ND	ND	ND	0.08	ND	0.43	ND	ND	ND	15 J	2	<1.8	No	<1	--
2/13/2018	HD-41	7.17	66.7	ND	0.045 J	ND	ND	ND	.011 J	0.00	0.88	0.37	ND	ND	ND	14 J	<1.8	<1.8	N/A	<1	--
3/6/2018	HD-41	7.13	70.3	ND	ND	ND	ND	ND	ND	0.01	ND	0.35	ND	ND	ND	18 J	<1.8	<1.8	N/A	<1	--
Discharges to M-004 (Outfall/Port #3)																					
1/11/2018	M-004	7.59	68.4	2.6	1.6 A07	ND	ND	ND	ND	0.08	ND	1.5	ND	ND	ND	21 J	13000	230	No	7.5	--
1/23/2018	M-004	8.23	73.6	--	0.042 J	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--
1/31/2018	M-004	7.96	75.4	--	0.16	--	--	--	--	0.06	--	--	--	--	--	--	--	--	--	--	--
2/7/2018	M-004	8.11	70.9	--	0.029 J	--	--	--	--	0.01	--	--	--	--	--	--	--	--	--	--	--
2/13/2018	M-004	8.03	69.6	1.7	0.15	ND	ND	ND	0.025 J	0.00	1.8	0.32	ND	ND	ND	26 J	7900	3300	Yes	>2420	--
3/6/2018	M-004	8.06	69.3	ND	ND	ND	ND	ND	0.016 J	0.00	ND	0.41	ND	ND	ND	16 J	2300	490	Yes	151.5	--
Discharges to M-005 (Outfall/Port #4)																					
1/11/2018	M-005	8.09	67.8	2.5	0.078 J	0.90 J	ND	ND	ND	0.03	0.89	1.8	140 A52	120 J, A57	ND	120	>160000	3500	No	>2420	--
1/23/2018	M-005	8.20	71.8	--	--	--	--	--	--	--	--	--	ND	ND	--	35 J	--	--	--	--	--
1/31/2018	M-005	8.14	73.2	--	--	--	--	--	--	0.04	--	--	ND	ND	--	62	--	--	--	--	--
2/7/2018	M-005	8.18	70.7	--	--	--	--	--	--	0.00	--	--	ND	ND	--	120	--	--	--	--	--
2/13/2018	M-005	8.21	66.9	ND	ND	ND	ND	ND	0.019 J	0.00	1.2	0.65	ND	ND	ND	30 J	54000	44.1	No	2419.6	--
2/22/2018	M-005	8.13	64.9	--	--	--	--	--	--	--	--	--	--	--	--	15 J	--	--	--	--	--
2/28/2018	M-005	8.19	63.7	--	--	--	--	--	--	--	--	--	--	--	--	28 J	--	--	--	--	--
3/6/2018	M-005	8.22	67.5	1.6	0.021 J	ND	ND	ND	0.013 J	0.00	ND	0.24	ND	ND	ND	18 J	92000	4600	No	816.4	--
Discharges to M-006 (Outfall/Port #5)																					
1/11/2018	M-006	8.36	68.4	ND	0.051 J	ND	ND	ND	ND	0.06	ND	0.35	36 J, A52	ND	ND	12 J	92000	790	No	>2420	--
2/13/2018	M-006	8.15	68.5	2.4	0.19	ND	ND	ND	0.011 J	0.00	1.1	0.39	ND	ND	ND	ND	2300	9.2	No	133.3	--
3/6/2018	M-006	8.21	68.5	1.7	0.015 J	ND	ND	ND	ND	0.02	ND	0.48	ND	ND	ND	ND	7900	79	No	816.4	--
Discharges to M-007 (Outfall/Port #5a)																					
1/11/2018	M-007	8.03	67.1	ND	ND	ND	ND	ND	ND	0.00	ND	0.19	ND	ND	ND	ND	330	2	No	7.5	--
2/13/2018	M-007	8.08	65.7	3.6	0.032 J, A07	ND	ND	ND	ND	0.00	0.75	0.24	ND	ND	ND	ND	49	<1.8	No	4.1	--
3/6/2018	M-007	8.05	66.4	3.1	ND	ND	ND	ND	ND	0.00	ND	0.19	ND	ND	ND	ND	130	130	Yes	26.6	--
Discharges to M-008 (Outfall/Port #5)																					
1/5/2018	M-008	8.45	68.2	--	--	--	--	--	--	0.20	--	--	--	--	--	--	--	--	--	--	--
1/11/2018	M-008	8.36	64.2	ND	ND	ND	ND	ND	ND	0.23	ND	0.31	ND	ND	ND	60	13000	310	No	217.8	--
1/17/2018	M-008	8.32	70.5	--	--	--	--	--	--	0.17	--	--	--	--	--	--	--	--	--	--	--
1/23/2018	M-008	8.35	69.1	--	--	--	--	--	--	0.09	--	--	--	--	--	70	--	--	--	--	--
1/31/2018	M-008	7.93	71.6	--	--	--	--	--	--	0.06	--	--	--	--	--	45 J	--	--	--	--	--
2/7/2018	M-008	8.65	69.8	--	--	--	--	--	--	0.05	--	--	--	--	--	45 J	--	--	--	--	--
2/13/2018	M-008	8.56	62.4	ND	0.021 J	ND	ND	ND	ND	0.02	0.75	0.49	ND	140 J	ND	110	790	7.8	No	29.2	--
2/22/2018	M-008	8.40	54.1	--	--	--	--	--	--	--	--	--	--	--	--	53	--	--	--	--	--
2/28/2018	M-008	8.03	66.0	--	--	--	--	--	--	--	--	--	ND	ND	--	56	--	--	--	--	--
3/6/2018	M-008	8.37	66.0	ND	ND	ND	ND	ND	ND	0.11	ND	0.22	ND	ND	ND	45 J	24000	280	No	1299.7	--
3/15/2018	M-008	8.35	65.5	--	--	--	--	--	--	0.24	--	--	--	--	--	37 J	--	--	--	--	--
3/23/2018	M-008	8.47	65.5	--	--	--	--	--	--	0.08	--	--	--	--	--	88	--	--	--	--	--
3/27/2018	M-008	8.35	69.3	--	--	--	--	--	--	0.01	--	--	--	--	--	49 J	--	--	--	--	--
Discharges to M-009 (Outfall/Port #5)																					
1/11/2018	M-009	8.03	68.7	ND	ND	ND	ND	ND	ND	0.00	0.56	0.17	ND	ND	ND	ND	1.8	<1.8	No	<1	--
2/13/2018	M-009	8.10	70.7	2.1	0.021 J	ND	ND	ND	ND	0.00	1.0	0.32	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
3/6/2018	M-009	7.84	75.4	ND	ND	ND	ND	ND	ND	0.03	ND	0.24	ND	ND	ND	ND	2	<1.8	No	<1	--
Discharges to M-010 (Outfall/Port #9)																					
1/11/2018	M-010	8.28	66.9	3.9	ND, A07	ND	ND	ND	ND	0.08	26	18	ND	ND	ND	ND	7900	13	No	113.7	--
Duplicate	M-010	8.28	66.9	2.2	ND	ND	ND	ND	ND	0.08	30	18	ND	ND	--	ND	2300	13	No	141.4	--
2/13/2018	M-010	8.29	65.8	3.2	ND	ND	ND	ND	ND	0.00	ND	0.49	ND	ND	ND	ND	1700	<1.8	No	5.2	--
3/6/2018	M-010	8.27	68.9	3.9	ND	ND	ND	ND	ND	0.00	ND	1.3	ND	ND	ND	ND	1400	4.5	No	95.9	--
Effluent Limit (Daily Max.)																					
Effluent Limit (Daily Max. if Fecal/Total Coliform > 0.1)																					
Effluent Limit (Monthly Avg.)																					

- = Not tested for
- = No established limit.
- ** = Acute Toxicity samples were collected on 1/21/15
- ND = none detected above laboratory
- NR = No reading taken
- J = Laboratory estimated value, below PQL and above the MDL.
- A = Laboratory PQLs were raised due to sample dilution caused by high analyte concentration or matrix interference.
- B = Indicates laboratory measurement.
- A01 = Detection and quantitation limits were raised due to sample dilution
- A52 = Chromatogram not typical of diesel
- A57 = Chromatogram not typical of motor oil
- A07 = Detection and quantitation limits were raised due to sample dilution caused by high analyte concentration or matrix interference.
- D = Chromatogram not typical of motor oil
- 1 = Chlorine test repeated after flow appeared to increase
- 2 = Area of coalescence that discharges through M-007

**SUMMARY OF WATER QUALITY MONITORING DATA
First Quarter (Jan.-Mar.) 2018**

INORGANIC NON-METALS (Aqueous Matrix)

Date Sampled	Sample Point	pH (Field Measured)	Temperature	Biochemical Oxygen Demand	Surfactants (MBAS)	Oil & Grease	Settleable Solids	Sulfides	Phenols	Residual Chlorine (Field Measured)	Total Suspended Solids	Turbidity	TPH Diesel	TPH Motor Oil	Bis(2-Ethylhexyl) Phthalate	Zinc	Total Coliform	Fecal Coliform	Fecal/Total Coliform >0.1?	Enterococcus	Acute Toxicity**
Units:			°F	mg/L	mg/L	mg/L	mL/L	mg/L	mg/L	mg/L	mg/L	NTU	µg/L	µg/L	µg/L	µg/L	MPN/100ml	MPN/100ml		MPN/100ml	% Survival
Discharges to M-001 (Outfall/Port #1a)																					
4/5/2018	M-001	8.35	57.9	ND	ND	ND	ND	ND	ND	0.00	ND	0.70	ND	ND	ND	22 J	3300	11	No	613.1	--
5/1/2018	M-001	8.42	58.5	1.9	ND, A07	ND	ND	ND	ND	0.00	0.67	0.98	ND	ND	ND	40 J	13000	49	No	93.3	--
6/4/2018	M-001	8.51	68.4	2	0.041 J	ND	ND	ND	ND	0.01	ND	0.28	ND	ND	ND	59	4900	220	No	410.6	--
6/14/2018	M-001	8.07	66.9	--	--	--	--	--	--	--	--	--	--	--	--	15 J	--	--	--	--	--
6/20/2018	M-001	8.29	66.9	--	--	--	--	--	--	--	--	--	--	--	--	180	--	--	--	--	--
6/26/2018	M-001	--	--	--	--	--	--	--	--	--	--	--	--	--	--	16	--	--	--	--	--
Discharges to M-002 (Outfall/Port #1)																					
4/5/2018	M-002	8.15	60.3	ND	ND	ND	ND	ND	ND	0.00	ND	0.33	ND	ND	ND	ND	490	<1.8	No	<1	--
5/1/2018	M-002	7.93	60.6	ND	ND	ND	ND	ND	ND	0.00	ND	0.24	ND	ND	ND	ND	1300	<1.8	No	7	--
6/4/2018	M-002	8.08	66.6	ND	ND	ND	ND	ND	ND	0.00	0.67	0.12	ND	ND	ND	ND	17000	<1.8	No	42.6	--
Discharges to M-003 (Outfall/Port #2)																					
4/5/2018	HD-41	7.43	64.0	ND	ND	ND	ND	ND	ND	0.00	ND	0.22	46 J, A52	280 A57	ND	9.8 J	2	<1.8	N/A	<1	--
4/19/2018	HD-41	7.70	74.3	--	--	--	--	--	--	--	--	--	100 J, A52	4100	--	--	--	--	--	--	--
4/25/2018	HD-41	7.16	70.2	--	--	--	--	--	--	--	--	--	ND	ND	--	--	--	--	--	--	--
5/1/2018	HD-41	7.13	63.7	ND	0.020 J	ND	ND	ND	ND	0.00	0.67	0.36	63, A52	ND, A57	ND	600	7000	<1.8	No	<1	--
5/11/2018	HD-41	6.98	65.1	--	--	--	--	--	--	--	--	--	ND	ND	--	9.6 J	--	--	--	--	--
5/16/2018	HD-41	7.20	69.4	--	--	--	--	--	--	--	--	--	ND	ND	--	13 J	--	--	--	--	--
5/24/2018	HD-41	7.10	71.4	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
5/29/2018	HD-41	7.34	77.2	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
6/4/2018	HD-41	7.20	71.2	--	--	--	--	ND	ND	0.02	--	--	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
Discharges to M-004 (Outfall/Port #3)																					
4/5/2018	M-004	7.77	65.5	ND	ND	ND	ND	ND	ND	0.00	ND	0.36	ND	ND	ND	ND	790	7.8	No	13.4	--
Duplicate	M-004	7.77	65.5	ND	ND	ND	ND	ND	ND	0.00	1.3	0.60	ND	ND	ND	51	>160000	3300	No	>2420	--
4/19/2018	M-004	8.35	67.1	--	--	--	--	--	--	--	--	--	--	--	--	210	--	--	--	--	--
4/25/2018	M-004	7.82	66.9	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
5/1/2018	M-004	7.86	66.0	ND	ND	ND	ND	ND	ND	0.00	ND	0.41	ND	ND	ND	13 J	35000	330	No	>2420	--
5/11/2018	M-004	7.83	67.3	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
5/16/2018	M-004	8.07	68.7	--	--	--	--	--	--	--	--	--	--	--	--	11 J	--	--	--	--	--
6/4/2018	M-004	7.98	70.3	ND	ND	ND	ND	ND	ND	0.04	ND	ND	ND	ND	ND	ND	310	33	Yes	67	--
Discharges to M-005 (Outfall/Port #4)																					
4/5/2018	M-005	8.12	66.7	ND	ND	ND	ND	ND	ND	0.00	ND	1.4	ND	ND	ND	150	13000	26	No	387.3	--
4/19/2018	M-005	8.45	66.2	--	--	--	--	--	--	--	--	--	--	--	--	46 J	--	--	--	--	--
4/25/2018	M-005	7.94	68.7	--	--	--	--	--	--	--	--	--	--	--	--	120	--	--	--	--	--
5/1/2018	M-005	8.06	66.9	ND	ND	ND	ND	ND	ND	0.00	0.78	0.35	29 J, A52	ND	ND	120	7900	330	No	261.3	--
Duplicate	M-005	8.06	66.9	ND	ND, A07	ND	ND	ND	ND	0.00	0.67	0.80	ND	ND	ND	100	4900	230	No	290.9	--
5/11/2018	M-005	8.08	66.0	--	--	--	--	--	--	--	--	--	--	--	--	15 J	--	--	--	--	--
5/16/2018	M-005	8.18	67.1	--	--	--	--	--	--	--	--	--	--	--	--	420	--	--	--	--	--
5/24/2018	M-005	8.04	68.2	--	--	--	--	--	--	--	--	--	--	--	--	12 J	--	--	--	--	--
5/29/2018	M-005	8.10	72.5	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
6/4/2018	M-005	8.18	70.9	ND	ND	ND	ND	ND	ND	0.00	ND	0.22	ND	ND	ND	15 J	160000	110	No	>2420	--
Discharges to M-006 (Outfall/Port #5)																					
4/5/2018	M-006	8.16	66.0	ND	ND	ND	ND	ND	ND	0.02	ND	0.73	ND	ND	ND	ND	280	13	No	23.1	--
5/1/2018	M-006	8.31	65.5	ND	ND	ND	ND	ND	ND	0.08	ND	0.82	ND	ND	ND	ND	3300	1100	Yes	193.5	--
6/4/2018	M-006	8.54	73.8	ND	ND	ND	ND	ND	ND	0.01	0.89	0.25	ND	ND	ND	ND	24000	24000	Yes	920.8	--
Duplicate	M-006	8.54	73.8	ND	ND	ND	ND	ND	ND	0.01	1.1	0.24	ND	ND	ND	ND	22000	22000	Yes	980.4	--
Discharges to M-007 (Outfall/Port #5a)																					
4/5/2018	M-007	8.18	66.2	3.4	ND	ND	ND	ND	ND	0.00	ND	0.23	ND	ND	ND	ND	490	490	Yes	25.9	--
5/1/2018	M-007	8.00	66.6	ND	ND	ND	ND	ND	ND	0.00	ND	0.28	ND	ND	ND	ND	46	4.5	Yes	32.7	--
6/4/2018	M-007	8.01	71.8	4.7	0.060 J	ND	ND	ND	ND	0.00	0.56	0.49	ND	ND	ND	ND	2300	2300	Yes	5.2	--
Discharges to M-008 (Outfall/Port #5)																					
4/5/2018	M-008	8.32	67.3	ND	ND	ND	ND	ND	ND	0.01	ND	2.0	ND	ND	ND	ND	11	<1.8	No	2	--
4/11/2018	M-008	8.03	73.0	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
4/19/2018	M-008	8.24	68.5	--	--	--	--	--	--	--	--	--	--	--	--	75	--	--	--	--	--
4/25/2018	M-008	7.95	66.2	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
5/1/2018	M-008	8.32	64.2	ND	ND	ND	ND	ND	ND	0.00	4.8	1.3	ND	ND	ND	15 J	7000	11	No	1986.3	--
5/11/2018	M-008	8.29	64.9	--	--	--	--	--	--	--	--	--	--	--	--	280	--	--	--	--	--
5/16/2018	M-008	8.31	66.4	--	--	--	--	--	--	--	--	--	--	--	--	79	--	--	--	--	--
5/24/2018	M-008	8.27	67.6	--	--	--	--	--	--	--	--	--	--	--	--	ND	--	--	--	--	--
5/29/2018	M-008	8.35	70.7	--	--	--	--	--	--	--	--	--	--	--	--	34 J	--	--	--	--	--
6/4/2018	M-008	8.25	75.0	ND	ND, A07	ND	ND	ND	ND	0.00	1.3	1.1	ND	ND	ND	ND	130	<1.8	No	4.1	--
Discharges to M-009 (Outfall/Port #5)																					
4/5/2018	M-009	7.99	69.1	ND	ND	ND	ND	ND	ND	0.00	ND	0.25	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
5/1/2018	M-009	7.88	69.1	ND	0.023 J	ND	ND	ND	ND	0.07	ND	0.92	ND	ND	1.0 J	30 J	<1.8	<1.8	N/A	4.1	--
6/4/2018	M-009	7.95	77.0	ND	0.021 J	ND	ND	ND	ND	0.00	1.0	0.34	ND	ND	ND	ND	<1.8	<1.8	N/A	<1	--
Discharges to M-010 (Outfall/Port #9)																					
4/5/2018	M-010	8.22	66.4	ND	ND	ND	ND	ND	ND	0.00	11	5.3	ND	ND	ND	ND	460	<1.8	No	52.9	--
5/1/2018	M-010	8.37	60.8	35	1.3 A07	ND	1.5	ND	0.082	0.08	770	310	1200 A01, A52	1200 A01, A57	ND	740	92000	7900	No	>2420	--
5/11/2018	M-010	8.22	66.9	4.5	0.21	--	ND	--	--	--	0.78	0.34	ND	ND	--	ND	--	--	--	--	--
5/16/2018	M-010	8.15	67.6	7.7	0.11 J, A07	--	ND	--	--	--	ND	0.59	ND	ND	--	15 J	--	--	--	--	--
5/24/2018	M-010	8.72	66.9	1.9	0.024 J	--	ND	--	--	--	ND	0.40	ND	ND	--	ND	--	--	--	--	--
5/29/2018	M-010	8.40	71.4	ND	ND	--	ND	--	--	--	ND	0.18	ND	ND	--	ND	--	--	--	--	--
6/4/2018	M-010	8.28	73.8	4.90	ND	ND	ND	ND	ND	0.00	ND	ND	ND	ND	ND	ND	1700	<1.8	No	51.2	--
Effluent Limit (Daily Max.)																					
				30	0.5	15	0.3	1.0	1.0												